



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: EILEEN

Ref: CS/INC24110617/Avh3m4(N)

Date: 28/02/2025

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SFC 788Z	<b>Veh. Inspected</b>	SLN 2328B
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1306227-001	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	JESS TOH	<b>Assign Date</b>	28/11/2024

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA COROLLA ALTIS	<b>c.c</b>	1598
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	MR053REH104560672	<b>Colour</b>	RED
<b>Odometer</b>	115203 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	215/45R17	CONTINENTAL	6 mm
<b>L/H Front Tyre</b>	215/45R17	CONTINENTAL	6 mm
<b>R/H Rear Tyre</b>	215/45R17	CONTINENTAL	6 mm
<b>L/H Rear Tyre</b>	215/45R17	CONTINENTAL	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	27/11/2024	<b>Inspect Date / Time</b>	28/11/2024 ( 02:42 PM )
<b>Survey held at</b>	ELITE AUTO RESTORATION PTE LTD 23 KAKI BUKIT AVE 4 #04-01, AAS KAKI BUKIT CENTRE SINGAPORE 415933		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**