

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600**Our File No:** CS/ICS24060306/UQH3E2**Date:** 26/07/2024REFERENCE

Insured/Claimant: LEE HAN ENGINEERING PTE LTD Policy No: MCV24A00021601

Date of Loss: 24/06/2024

Nature of Claim: OD

Claim No: DMCV2400130H/ST/PREMIUM OS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GQ2325C**

Make & Model: NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD
EURO 5 (M)

Reg. Date: 24/03/2016 (Man. Year: 2016)

Colour: Gold

Engine Capacity: 2953 cc

Market Value/New Car Price: S\$20,000.00

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: ZD30009550N

Chassis No: JN1SC2F24Z0858274

Odometer: 264956 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 165 R13 (D)

Front Left Side: Giti 6 mm Rear Left Side: Dunlop 6/6 mm

Front Right Side: Giti 6 mm Rear Right Side: Dunlop 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,613.13	3,190.00	1,423.13	30.85
Miscellaneous Items	162.00	178.20	-16.20	-10.00
Labour	1,320.00	420.00	900.00	68.18
Paintwork Labour	1,200.00	550.00	650.00	54.17
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,295.13	4,338.20	2,956.93	40.53
Approved Total (Overridden) (S\$)		3,450.00		
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	7,295.13	2,850.00	4,445.13	60.93
+ GST 9.00/9.00% (S\$)	656.56	256.50	400.06	60.93
Nett Amount (S\$)	7,951.69	3,106.50	4,845.19	60.93

INSPECTION

Date of Assignment: 27/06/2024

Date Inspected: 02/07/2024 Inspected At:

3021A Ubi Road 1 #01-36

Repairer: Automobile Integrated Management Pte Ltd
(HQ)

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Jul 2024)	
Parts:	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GQ2325C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Wiper panel, front (WCP)	Dented	350.00 F	*350.00 F
2	1		*Headlamp LH (WCP)	Cracked	350.00 F	*350.00 F
3	1		*Headlamp corner panel (WCP)	Dented	275.00 F	*275.00 F
4	1		*Headlamp lower panel (WCP)	Cracked	68.75 F	*68.75 F
5	1		*Bumper, front (WCP)	Grazed	600.00 F	*600.00 F
6	1		*side mirror assy LH (WCP)	Repair	375.00 F	*- F
7	1		*side mirror cover LH (WCP)	Cracked / Damaged	93.75 F	*93.75 F
8	1		*Door LH, front (WCP)	Dented / Twisted	812.50 F	*812.50 F
9	1		*panel center, front (WCP)	Repair	875.00 F	*- F
10	1		*Cabstar badge (WCP)	Serviceable	43.75 F	*- F
11	1		*grille center, front (WCP)	Cracked	350.00 F	*350.00 F
						F=Franchise part.
					Sub Total (S\$)	4,193.75 2,900.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	419.38 290.00
					Total Parts (S\$)	4,613.13 3,190.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Supplementary #1</u>				
1	1	Step garnish LH (CRACKED) (COST PLUS 10%) (WCP)	162.00	178.20
Sub Total (S\$)			162.00	178.20

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	SPRAY PAINTING	New	1,200.00	550.00
<u>Labour Items</u>				
2	PANEL BEATING	New	1,200.00	400.00
3	WIRING	New	120.00	20.00
Gross Labour Cost (S\$)			2,520.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >