

FALCON AIR AUTO SERVICES PTE LTD

Page 1 / 2

Tel No. :

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER S(079909)

Attention : Motor Claim Department

Contact : 63896111 Fax No. : 62221033

Estimate : ES709725

Date : 02/12/2024

Vehicle Num. : SLS9799C

Make/Model : TOYOTA SIENTA

Chassis/Eng# : MHFZ28H380004094

Accident Date : 28/11/2024

Claim No. :

Reference :

Policy No. :

Not Authorized
in
motor
2/12/24
2/12/24 3700/
4 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1 PC	N/S HEADLAMP		1,863.00
2.	1 PC	RADIATOR GRILLE		1,047.00
3.	1 PC	FRONT BUMPER		715.00
4.	1 PC	N/S FRONT BUMPER SIDE RETAINER		86.00
5.	1 PC	N/S FRONT FOG LAMP		486.00
6.	1 PC	N/S FRONT FOG LAMP GARNISH		256.00
7.	1 PC	FRONT BUMPER REINFORCEMENT		815.00
8.	1 PC	AIR RESONATOR PIPE		197.00
9.	1 PC	AIR CON CONDENSER		2,486.00
10.	1 PC	RADIATOR GRILLE CHROME		298.00
List TotalS\$:				8,249.00
25.00% Discount S\$:				2,062.25
				6,186.75
SPECIAL NETT ITEMS :				
1.	1 PC	FRONT BUMPER CLIP		40.00
2.	1 PC	FRONT BUMPER RIVET		60.00
3.	1 PC	FRONT NUMBER PLATE		45.00
Special Nett Total S\$:				145.00

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Page 2 / 2

Tel No. :

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER S(079909)

Attention : Motor Claim Department
Contact : 63896111 Fax No. : 62221033

Estimate : ES709725

Date : 02/12/2024
Vehicle Num. : SLS9799C
Make/Model : TOYOTA SIENTA
Chassis/Eng# : MHFZ28H380004094
Accident Date : 28/11/2024
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :
TO FOCUS HEADLAMP & WIRING
TO VACCUM, REOIL AND REGAS AIR CON
TO RUST PROOF PANELS
TO APPLY BODY SEALANT ON BODY JOINTS
TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, REPLACEMENT
OF PARTS AND ALIGN THE SAME
TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA

	50.00	20
11	120.00	X
11	250.00	X
11	250.00	X
	750.00	400
	750.00	520
	2,170.00	

Labour Total S\$:

E. & O.E.

Total S\$: 8,501.75

=====

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p- 4814.1
252
3610.58
80
940
4630.58
222
3704