

CHIA AUTO SERVICES PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6243 1373

Reg. No: 201538764H

Email: CA3SERVICES@GMAIL.COM

2021
AGH300316940

ATTENTION:	MOTOR CLAIMS DEPARTMENT
DATE:	29-11-24
CLAIM TYPE:	T/P CLAIM
TO:	INDIA <i>Daphne.</i>
VEHICLE DETAILS	
VEHICLE NO:	SNN6805R
MAKE & MODEL:	TOYOTA ALPHARD
CHASSIS NO:	
ACCIDENT DETAILS	
DATE:	27 November, 2024
TIME:	2200HRS
THIRD PARTY REQUESTOR:	JACK LI

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 2,155.30	\$ 2,155.30
2	TAILGATE LOGO <i>New</i>	1	\$ 95.00	\$ 95.00
3	TAILGATE ALPHARD EMBLEM <i>new</i>	1	\$ 90.00	\$ 90.00
4	TAILGATE DAMPER <i>new</i>	2	\$ 90.00	\$ 180.00
5	TAILGATE HINGE <i>New</i>	2	\$ 280.00	\$ 560.00
6	TAILGATE LAMP LH <i>cracked.</i>	1	\$ 890.00	\$ 890.00
7	TAILGHATE INNER TRIM BOARD <i>cracked</i>	1	\$ 1,155.20	\$ 1,155.20
8	TAILGATE SIDE SENSOR LH <i>Best</i>	1	\$ 1,255.30	\$ 1,255.30
9	TAILGATE LOCK <i>new</i>	1	\$ 520.00	\$ 520.00
10	TAILGATE WEATHERSTRIP <i>new</i>	1	\$ 350.00	\$ 350.00
11	TAILGATE ANTENNA SWITCH <i>new</i>	1	\$ 180.00	\$ 180.00
12	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 250.00	\$ 250.00
13	REAR BUMPER <i>Distorted</i>	1	\$ 880.00	\$ 880.00
14	REAR BUMPER TOWING COVER LH <i>Distorted</i>	1	\$ 80.00	\$ 80.00
15	REAR BUMPER SIDE RETAINER LH <i>cracked</i>	1	\$ 110.00	\$ 110.00
16	REAR BUMPER REFLECTOR LH <i>cracked</i>	1	\$ 150.00	\$ 150.00
17	REAR PARKING SENSOR <i>Distorted</i>	1	\$ 320.00	\$ 320.00
18	REAR QUARTER BUMPER LH <i>Distorted</i>	1	\$ 350.00	\$ 350.00
19	REAR QUARTER BUMPER SIDE RETAINER LH <i>new</i>	1	\$ 130.00	\$ 130.00
20	TAILLAMP LH <i>cracked</i>	1	\$ 1,055.30	\$ 1,055.30
21	REAR FENER INNER TRIM LH <i>cracked</i>	1	\$ 1,355.60	\$ 1,355.60

✓
 +
 ✓
 +
 +
 789.
 855
 - 940
 +
 x
 x
 -
 - 25
 ✓
 ✓
 ✓
 ✓
 +
 ✓ 940
 ✓

22	REAR END PANEL <i>Dented</i>	1	\$ 860.00	\$ 860.00	✓
23	REAR END PANEL TOP GARNISH <i>dented</i>	1	\$ 250.00	\$ 250.00	✓
24	REAR FLOOR PANEL <i>Ryze</i>	1	\$ 980.00	\$ 980.00	+
25	REAR FLOOR PANEL MAT <i>new</i>	1	\$ 1,155.20	\$ 1,155.20	+
26	REAR COMPARTMENT COVER LH <i>dented</i>	1	\$ 560.00	\$ 560.00	280.

Rear Bumper under cover LH #280

dented 10939 510

820492

TOTAL PRICE \$ 15,916.90

LESS 25% \$ 3,979.23

SUB TOTAL PRICE \$ 11,937.68

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	TAILGATE INNER TRIM BOARD CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
3	TAILGATE SIDE SENSOR CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	-
4	TAILGATE WINDSCREEN SELANT <i>new</i>	1	\$ 100.00	\$ 100.00	60
5	REAR BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
6	REAR FENDER INNER TRIM CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
7	REAR END PANEL SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00	60.
8	REAR END PANEL TOP GARNISH CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
9	REAR FLOOR PANEL SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00	+
10	REAR FLOOR PANEL MAT CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	+
TOTAL				\$ 510.00	220

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 2,000.00	\$ 2,000.00	800.
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 2,000.00	\$ 2,000.00	800
3	TUFF COAT	1	\$ 200.00	\$ 200.00	80
4	WIRING CHECK	1	\$ 80.00	\$ 80.00	30
5	TO REMOVE AND REFIX INNER CAR CUSHION	1	\$ 180.00	\$ 180.00	80
6	TO REMOVE AND REFIX TAILGATE MECHANISM	1	\$ 180.00	\$ 180.00	80
7	TO REMOVE AND REFIX REVERSE SENSOR AND SETTING	1	\$ 100.00	\$ 100.00	50
8	TO REMOVE AND REFIX REVERSE CAMERA AND SETTING	1	\$ 100.00	\$ 100.00	50
9	TO REMOVE AND REFIX REAR WINDSCREEN	1	\$ 120.00	\$ 120.00	✓

TOTAL \$ 4,960.00

ESTIMATE REPORT

TOTAL PARTS COST \$ 12,447.68

2090

TOTAL LABOUR COST \$ 4,960.00
TOTAL REPAIR COST \$ 17,407.68

APPROVED DETAILS:

SURVEYOR:
CONTACT NO.:
PART BY PART/LUMP SUM
NO. OF DAYS

Adrian King,
w/s 29/11/24.
06 Days.

total: 10514.92

L/S: 8.4K

8.4K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: