



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD ONE RAFFLES QUAY #25-01 NORTH TOWER SINGAPORE 048583 ATTN: TED SEAH			Ref: CS/LIP24110624/Eqh3e2(N) Date: 24/01/2025 Code: LIP	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SLH 2742U	Veh. Inspected	GBJ 3774D
	Policy No.		Coverage (\$)	0.00
	Claim No.	IVS24/2185	Excess (\$)	0.00
	Assign From	TED SEAH	Assign Date	28/11/2024
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA DYNA 150	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	JTFAT35Y40K212603	Colour	WHITE
	Odometer	237961 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	YOKOHAMA	5 mm
	L/H Front Tyre	195 R15C	YOKOHAMA	5 mm
	R/H Rear Tyre	195 R15C	YOKOHAMA	5 mm
	L/H Rear Tyre	195 R15C	YOKOHAMA	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	21/11/2024	Inspection Date	04/12/2024
	Survey held at	U E MOTOR BLK 3006, UBI ROAD 1 #01-334 SINGAPORE 408700		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	