



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: JEFF LIN

Ref: CS/INC24110627/Anh3m4(N)

Date: 22/01/2025

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GBK 9683M	<b>Veh. Inspected</b>	SME 913K
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1306254-002	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ANNIE KOH	<b>Assign Date</b>	28/11/2024

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	mitsubishi outlander	<b>c.c</b>	1998
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2020
<b>Chassis No.</b>	GF7W0602183	<b>Colour</b>	SILVER
<b>Odometer</b>	77107 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	225/55R18	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	225/55R18	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	225/55R18	BRIDGESTONE	6 mm
<b>L/H Rear Tyre</b>	225/55R18	BRIDGESTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	28/11/2024	<b>Inspect Date / Time</b>	29/11/2024 ( 12:48 PM )
<b>Survey held at</b>	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**