

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TP INC
Hui Rong

TAX INVOICE

AHMAD KHUSHAIRI BIN ABIDIN
BLK 444 TAMPINES ST 42 #02-136
SINGAPORE 520444

Repair Code : CLM16494

Date in : 28/11/2024

Vehicle Num. : SME913K

Model : MITSUBISHI OUTLANDER 2.0 CVT

Chassis/Eng# : GF7W0602183/4J11BN0108

Contact : 90235295

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Distorted</i>	1	896.00	✓ 896.00
REAR BUMPER LOWER LID <i>Distorted</i>	1	501.00	✓ 501.00
REAR BUMPER LOWER LID CLIPS <i>new</i>	12	3.00	✓ 36.00
REAR BUMPER REFLECTOR L/R <i>changed</i>	2	90.00	✓ 180.00
REAR BUMPER REINFORCEMENT BRACKET L/R <i>Dented</i>	2	71.00	✓ 142.00
REAR BUMPER SIDE GARNISH L/R (ARCH) <i>changed new</i>	2	128.00	✓ 256.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	25.00	✓ 50.00
REAR END PANEL <i>Dented</i>	1	550.00	✓ 550.00
REAR END PANEL ANTENNA SENSOR <i>changed</i>	1	100.00	✓ 100.00
REAR END PANEL BUZZLE SENSOR <i>changed</i>	1	95.00	✓ 95.00
REAR END PANEL INNER TOP GARNISH <i>changed</i>	1	158.00	✓ 158.00
REAR END SIDE PANEL L/R <i>Repair</i>	2	105.00	✓ 210.00
REAR EXHAUST SILENCER BOX <i>Repair</i>	1	769.00	✓ 769.00
REAR FENDER INNER TRIM BOARD L/R <i>new</i>	2	927.00	✓ 1,854.00
REAR FLOOR PANEL <i>Repair</i>	1	714.00	✓ 714.00
REAR FLOOR PANEL CARGO TRAY BOX <i>changed</i>	1	368.00	✓ 368.00
REAR FLOOR PANEL TOP BOARD COVER <i>new</i>	1	266.00	✓ 266.00
REAR TAILGATE <i>Dented</i>	1	1014.00	✓ 1,014.00

884

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

AHMAD KHUSHAIRI BIN ABIDIN
 BLK 444 TAMPINES ST 42 #02-136
 SINGAPORE 520444

Contact : 90235295

TAX INVOICE

Repair Code : CLM16494

Date in : 28/11/2024

Vehicle Num. : SME913K

Model : MITSUBISHI OUTLANDER 2.0 CVT

Chassis/Eng# : GF7W0602183/4J11BN0108

REAR TAILGATE 'C&C' EMBLEM	1	88.00	✓	88.00
REAR TAILGATE 'LOGO' EMBLEM	1	42.00	✓	42.00
REAR TAILGATE 'MIVEC' EMBLEM	1	85.00	✓	85.00
REAR TAILGATE 'OUTLANDER' EMBLEM	1	86.00	✓	86.00
REAR TAILGATE AUTO LOCK SENSOR L/R	2	496.00	+	992.00
REAR TAILGATE HINGES L/R	2	30.00	+	60.00
REAR TAILGATE INNER PULL HANDLE	1	182.00	+	182.00
REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R	2	18.00	+	36.00
REAR TAILGATE INNER TRIM BOARD	1	450.00	✓	450.00
REAR TAILGATE LOCK STRIKER	1	28.00	x	28.00
REAR TAILGATE MECHANISM LOCK	1	428.00	✓	428.00
REAR TAILGATE NUMBER PLATE LAMP L/R	2	35.00	+	70.00
REAR TAILGATE OUTER GARNISH	1	466.00	✓	466.00
REAR TAILGATE REFLECTOR L/R	2	397.00	+	794.00
REAR TAILGATE WEATHER STRIP	1	192.00	✓	192.00
REAR TAILGATE WINDSCREEN MOULDING L/R	2	38.00	✓	76.00
REAR TAILGATE WINDSCREEN MOULDING U/L	2	55.00	✓	110.00
REAR TAILLAMP L/R	2	680.00	✓	1,360.00

1012

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

AHMAD KHUSHAIRI BIN ABIDIN
 BLK 444 TAMPINES ST 42 #02-136
 SINGAPORE 520444

Contact : 90235295

TAX INVOICE

Repair Code : CLM16494

Date in : 28/11/2024

Vehicle Num. : SME913K

Model : MITSUBISHI OUTLANDER 2.0 CVT

Chassis/Eng# : GF7W0602183/4J11BN0108

		Subtotal before discount	6945	13,704.00
Percentage discount 10%			6250.50	1,370.40
		Sub-total 1		12,333.60
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	30	80.00
REAR BUMPER REVERSE SENSOR - SET <i>new</i>	1	280.00	20	280.00
REAR BUMPER SIDE SPOILER L/R <i>new</i>	2	450.00	60	900.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>new</i>	1	50.00	20	50.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET <i>new</i>	2	50.00	30	100.00
REAR FLOOR PANEL INSULATOR MAT <i>new</i>	1	300.00	+	300.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	30	50.00
REAR TAILGATE NUMBER PLATE <i>new</i>	1	25.00	+	25.00
REAR TAILGATE NUMBER PLATE HOLDER <i>new</i>	1	50.00	+	50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET <i>new</i>	1	60.00	20	60.00
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	80.00	60	80.00
REAR TAILLAMP CLIPS L/R - SET <i>new</i>	2	25.00	+	50.00
		Subtotal before discount		2,025.00
Percentage discount 0%				0.00
		Sub-total 2		2,025.00
		Parts-total		14,358.60

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

AHMAD KHUSHAIRI BIN ABIDIN
BLK 444 TAMPINES ST 42 #02-136
SINGAPORE 520444

Contact : 90235295

TAX INVOICE

Repair Code : CLM16494

Date in : 28/11/2024

Vehicle Num. : SME913K

Model : MITSUBISHI OUTLANDER 2.0 CVT

Chassis/Eng# : GF7W0602183/4J11BN0108

LABOUR

To reset system after repair works	400.00
To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	80.00
To remove, reinstall tailgate windscreen	120 150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60 100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	700 1,300.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	60 100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	800 1,100.00
To apply anti-rust chemical on repaired and replaced panel.	60 120.00
To remove, reinstall tailgate mechanism and check for function	60 80.00
Labour Total	3,430.00
Parts & Labour Total	17,788.60

*** This is a computer-generated document which requires no signature.***

page 4

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Handwritten signature
L/S 29/11/24

06 hrs

Total: 9180.50

L/S: 73K ✓