



FALCON-AIR

UNITED OVERSEAS INSURANCE LTD
146 ROBINSON ROAD #02-01
UOI BUILDING
068909
Attn : MOTOR CLAIMS DEPT
Tel : 6222 7733

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg No: 199501140D
GST Reg No: 199501140D

1 of

Not Withheld
L1 By 8
Running After Rain

Ex 2800

8 days

Estimate : ES000064
Date : 27/06/2024
Vehicle No. : SKV7359Z
Vehicle Model : MAZDA BIANTE 5-DOOR WAGON
2.0L SP.6EAT
Chassis No. : JM6CC1071G0108552
Accident Date : 23/06/2024
Claim No. :
Reference : O/D
Policy No. : DHOM130006362300
Page : 1 of 3

Item	Qty	Description	Unit Price S\$	Amount S\$
1.	1	BONNET	430.00	<i>B</i> 473.00 ✓
2.	1	BONNET LOCK	95.00	<i>Dir</i> 104.50 ✓
3.	2	BONNET HINGE	32.00	70.40 ✓
4.	1	BONNET INSULATOR CLIP	50.00	<i>M</i> 50.00 ✓
5.	2	HEADLAMP	<i>mf CM</i> 1,100.00	2,420.00 ✓
6.	1	RADIATOR SUPPORT PANEL	280.00	<i>CM</i> 308.00 ✓
7.	1	RADIATOR AUTO	<i>hous Bu</i> 410.00	414.10 ✓
8.	1	RADIATOR SPARE TANK	65.00	71.50 ✓
9.	1	RADIATOR FAN COWLING ASSY	575.00	632.50 ✓
10.	1	FRONT BRACE PANEL	30.00	33.00 ✓
11.	1	TOW COVER	20.00	<i>nd</i> 22.00 ✓
12.	1	AIR CON CONDENSER	600.00	660.00 ✓
13.	1	FRONT GRILLE ASSY	900.00	<i>CM</i> 990.00 ✓
14.	1	FRONT GRILLE LOGO	48.00	<i>bu</i> 52.80 ✓
15.	1	INTAKE MANIFOLD	680.00	748.00 ✓
16.	1	FRONT BUMPER	730.00	<i>B</i> 803.00 ✓
17.	2	FRONT BUMPER SIDE RETAINER	25.00	55.00 ✓
18.	1	FRONT BUMPER REINFORCEMENT	265.00	<i>B</i> 291.50 ✓

Continue to Next Page

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)



FALCON-AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co Reg No 1995011400
ST Reg No 1995011400

1 of

UNITED OVERSEAS INSURANCE LTD

146 ROBINSON ROAD #02-01

UOI BUILDING

068909

Attn : MOTOR CLAIMS DEPT

Tel : 6222 7733

Date : 27/06/2024
Vehicle No. : SKV7359Z
Vehicle Model : MAZDA BIANTE 5-DOOR WAGON
2.0L SP.6EAT
Chassis No. : JM6CC1071G0108552
Accident Date : 23/06/2024
Claim No. :
Reference : O/D
Policy No. : DHOM130006362300
Page : 2 of 3

Item	Qty	Description	Unit Price S\$	Amount S\$
19.	2	FRONT BUMPER TOP CHROME	241 CM 195.00	429.00 ✓
20.	2	FRONT BUMPER LOWER CHROME STICKER	Me 48.00	105.60 ✓
21.	1	FRONT BUMPER CLIP	Me 60.00	60.00 ✓
22.	1	FRONT NUMBER PLATE	Me 45.00	45.00 ✓
23.	1	FRONT BUMPER UNDER COVER	Me 65.00	71.50 X
24.	1	FRONT ENGINE UNDERCOVER	Me 185.00	203.50 X
25.	2	HEADLAMP LOWER BRACKET	65.00	143.00 7
26.	1	TAILGATE	Me 750.00	825.00 ✓
27.	1	TAILGATE GLASS INNER MOULDING	Me 40.00	40.00 X
28.	1	TAILGATE SEALANT	Me 45.00	45.00 ✓
29.	1	TAILGATE EMBLEM - SKYACTIV	40.00	44.00 ✓
30.	1	TAILGATE CHROME HANDLE	235.00	258.50 7
31.	1	TAILGATE CENTRE GARNISH (WITH LOGO)	750.00	825.00 ✓
32.	7	CLIP FASTENER	2.00	15.40 ✓
33.	2	CLIP STOPPER	10.00	22.00 X
34.	1	REAR BUMPER	485.00	533.50 ✓
35.	1	REAR BUMPER CLIP	60.00	60.00 ✓
36.	1	REAR BUMPER CENTRE CHROME STICKER	85.00	93.50 ✓

Continue to Next Page

FALCON - AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-05/07/13 #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(525840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110



FALCON - AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No. 199501140D
GST Reg. No. 199501140D

1 of

UNITED OVERSEAS INSURANCE LTD

146 ROBINSON ROAD #02-01

UOI BUILDING

068909

Attn : MOTOR CLAIMS DEPT

Tel : 6772 7733

Estimate : ES000064

Date : 27/06/2024

Vehicle No. : SKV7359Z

Vehicle Model : MAZDA BIANTE 5-DOOR WAGON
2.0L SP.6EAT

Chassis No. : JM6CC1071G0108552

Accident Date : 23/06/2024

Claim No. :

Reference : O/D

Policy No. : DHOM130006362300

Page : 3 of 3

Item	Qty	Description	Unit Price S\$	Amount S\$
37.	2	REAR BUMPER CHROME STICKER	55.00	121.00
38.	1	REVERSE SENSOR	250.00	250.00
39.	1	TO REMOVE/REFIX REVERSE SENSOR TO NEW BUMPER	50.00	50.00
40.	1	TO TRANSFER TAILGATE MECHANISM	100.00	100.00
41.	1	TO FOCUS HEADLAMP AND CHECK WIRING	50.00	50.00
42.	1	TO VACUUM, REOIL AND REGAS AIR CON	120.00	120.00
43.	1	TO REMOVE/REFIX TAILGATE GLASS	120.00	120.00
44.	1	TO REMOVE/REPLACE RADIATOR SUPPORT PANEL, REPAIR FRONT FENDERS, FRONT INNER PANEL, REAR END PANEL INCLUDING REPLACEMENT OF PARTS	1,400.00	1,400.00
45.	1	TO SPRAY PAINTING ON BONNET, BONNET HINGES, LH/RH FRONT FENDERS, FRONT INNER PANEL, FRONT BUMPER, TAILGATE, REAR END PANEL, REAR BUMPER	1,700.00	1,700.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total	S\$	15,929.8
GST @ 9%	S\$	1,433.0
Total	S\$	17,363.0

SINGAPORE DOLLAR SEVENTEEN THOUSAND THREE HUNDRED SIXTY THREE AND CENTS FORTY EIGHT ONLY

Notes :

1. All cheques should be crossed and made payable to FALCON-AIR AUTO SERVICES PTE LTD
2. Goods sold are neither returnable nor refundable. Otherwise a cancellation fee of 20% on purchase price will be imposed.

Accepted by

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)