



FALCON-AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No: 199501140D
GST Reg. No: 199501140D

1 of 1

UNITED OVERSEAS INSURANCE LTD

146 ROBINSON ROAD #02-01

UOI BUILDING

068909

Attn: MOTOR CLAIMS DEPT

Tel: 6222 7733

Not Withheld
21 Pym &
Running After Paim

Ex & 8001

8 days

4/5 & 10, 7001

Estimate : ES000064
Date : 27/06/2024
Vehicle No. : SKV7359Z
Vehicle Model : MAZDA BIANTE 5-DOOR WAGON
2.0L SP.6EAT
Chassis No. : JM6CC1071G0108552
Accident Date : 23/06/2024
Claim No. :
Reference : O/D
Policy No. : DHOM130006362300
Page : 1 of 3

Item	Qty	Description	Unit Price S\$	Amount S\$
1.	1	BONNET	430.00	<i>By</i> 473.00
2.	1	BONNET LOCK	95.00	<i>Div</i> 104.50
3.	2	BONNET HINGE	32.00	<i>Dis</i> 70.40
4.	1	BONNET INSULATOR CLIP	50.00	<i>Me</i> 50.00
5.	2	HEADLAMP	<i>mg CM</i> 1,100.00	2,420.00
6.	1	RADIATOR SUPPORT PANEL	280.00	<i>CM</i> 308.00
7.	1	RADIATOR AUTO	<i>hours Pru</i> 410.00	414.10
8.	1	RADIATOR SPARE TANK	<i>Red</i> 65.00	71.50
9.	1	RADIATOR FAN COWLING ASSY	<i>CM</i> 575.00	632.50
10.	1	FRONT BRACE PANEL	30.00	<i>By</i> 33.00
11.	1	TOW COVER	20.00	<i>Red</i> 22.00
12.	1	AIR CON CONDENSER	600.00	<i>Pru</i> 660.00
13.	1	FRONT GRILLE ASSY	900.00	<i>CM</i> 990.00
14.	1	FRONT GRILLE LOGO	48.00	<i>Red</i> 52.80
15.	1	INTAKE MANIFOLD	680.00	<i>Sur</i> 748.00
16.	1	FRONT BUMPER	730.00	<i>By</i> 803.00
17.	2	FRONT BUMPER SIDE RETAINER	25.00	<i>Svc</i> 55.00
18.	1	FRONT BUMPER REINFORCEMENT	265.00	<i>By</i> 291.50

Continue to Next Page

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON - AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
ST Reg. No.: 199501140D

1 of

UNITED OVERSEAS INSURANCE LTD

146 ROBINSON ROAD #02-01

UOI BUILDING

068909

Attn : MOTOR CLAIMS DEPT

Tel : 6222 7733

Date : 27/06/2024
Vehicle No. : SKV7359Z
Vehicle Model : MAZDA BIANTE 5-DOOR WAGON
2.0L SP.6EAT
Chassis No. : JM6CC1071G0108552
Accident Date : 23/06/2024
Claim No. :
Reference : O/D
Policy No. : DHOM130006362300
Page : 2 of 3

Item	Qty	Description	Unit Price S\$	Amount S\$
19.	2	FRONT BUMPER TOP CHROME	245 CM 195.00	429.00
20.	2	FRONT BUMPER LOWER CHROME STICKER	M 48.00	105.60
21.	1	FRONT BUMPER CLIP	M 60.00	60.00
22.	1	FRONT NUMBER PLATE	R 45.00	45.00
23.	1	FRONT BUMPER UNDER COVER	P 65.00	71.50
24.	1	FRONT ENGINE UNDERCOVER	L 185.00	203.50
25.	2	HEADLAMP LOWER BRACKET	CRA 65.00	143.00
26.	1	TAILGATE	R 750.00	825.00
27.	1	TAILGATE GLASS INNER MOULDING	N 40.00	40.00
28.	1	TAILGATE SEALANT	M 45.00	45.00
29.	1	TAILGATE EMBLEM - SKYACTIV	40.00	M 44.00
30.	1	TAILGATE CHROME HANDLE	S 235.00	258.50
31.	1	TAILGATE CENTRE GARNISH (WITH LOGO)	750.00	CRA 825.00
32.	7	CLIP FASTENER	2.00	M 15.40
33.	2	CLIP STOPPER	10.00	S 22.00
34.	1	REAR BUMPER	485.00	R 533.50
35.	1	REAR BUMPER CLIP	60.00	M 60.00
36.	1	REAR BUMPER CENTRE CHROME STICKER	85.00	M 93.50

Continue to Next Page

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON - AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

1 of

UNITED OVERSEAS INSURANCE LTD

146 ROBINSON ROAD #02-01
UOI BUILDING
068909
Attn: MOTOR CLAIMS DEPT
Tel: 6222 7733

Estimate : ES000064
Date : 27/06/2024
Vehicle No. : SKV7359Z
Vehicle Model : MAZDA BIANTE 5-DOOR WAGON
2.0L SP.6EAT
Chassis No. : JM6CC1071G0108552
Accident Date : 23/06/2024
Claim No. :
Reference : O/D
Policy No. : DHOM130006362300
Page : 3 of 3

Item	Qty	Description	Unit Price S\$	Amount S\$
37.	2	REAR BUMPER CHROME STICKER	55.00	121.00
38.	1	REVERSE SENSOR	250.00	250.00
39.	1	TO REMOVE/REFIX REVERSE SENSOR TO NEW BUMPER	50.00	50.00
40.	1	TO TRANSFER TAILGATE MECHANISM	100.00	100.00
41.	1	TO FOCUS HEADLAMP AND CHECK WIRING	50.00	50.00
42.	1	TO VACUUM, REOIL AND REGAS AIR CON	120.00	120.00
43.	1	TO REMOVE/REFIX TAILGATE GLASS	120.00	120.00
44.	1	TO REMOVE/REPLACE RADIATOR SUPPORT PANEL, REPAIR FRONT FENDERS, FRONT INNER PANEL, REAR END PANEL INCLUDING REPLACEMENT OF PARTS	1,400.00	1,400.00
45.	1	TO SPRAY PAINTING ON BONNET, BONNET HINGES, LH/RH FRONT FENDERS, FRONT INNER PANEL, FRONT BUMPER, TAILGATE, REAR END PANEL, REAR BUMPER	1,700.00	1,700.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

SINGAPORE DOLLAR SEVENTEEN THOUSAND THREE HUNDRED SIXTY THREE AND CENTS FORTY EIGHT ONLY

Acknowledged by Repairer	Sub Total	S\$	15,929.80
Signature:	GST @ 9%	S\$	1,433.68
Date:	Total	S\$	17,363.48

Notes:

1. All cheques should be crossed and made payable to FALCON-AIR AUTO SERVICES PTE LTD
2. Goods sold are neither returnable nor refundable. Otherwise a cancellation fee of 20% on purchase price will be imposed.

Accepted by

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg