

KING'S WAY AUTOMOTIVE PTE LTD

Company Registration No. 202440629G
435B Northshore Drive #07-1523 Singapore 822435
Email : kingswayclaim@gmail.com

Tel : 81890682

LKK Auto Consultants hence notify

the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

MING TEIK CO PTE LTD
12 SURREY ROAD #01-01
SURREY COURT
SINGAPORE 307750

ESTIMATE

Accident Date: 28/11/2024

Vehicle No.: SLJ6753B

Model: VOLKSWAGEN CADDY MAXI 1.4 TSI AT SAJHK5

Chassis/Eng#: WV2ZZZ2KZGX129451/CZC606820

Acknowledged by Repairer

Date:

No	Description Of Parts		Qty	Unit Price	Amount
1	REAR TAILGATE	L	1	20/400	\$ 2,699.00
2	REAR TAILGATE HINGES L/R	L	2	11	\$ 253.20
3	REAR TAILGATE DAMPER L/R	L	2	10	\$ 411.60
4	REAR TAILGATE WINDSCREEN MOULDING 118	L	1	200	\$ 207.77
5	REAR TAILGATE 'CADDY' EMBLEM 115	L	1	100	\$ 175.20
6	REAR TAILGATE 'TSI' EMBLEM	L	1	100	\$ 108.00
7	REAR TAILGATE 'BLUEMOTION' EMBLEM	L	1	50	\$ 153.42
8	REAR TAILGATE 'LOGO' EMBLEM	L	1	10	\$ 180.70
9	REAR TAILGATE OUTER CHROME MOULDING	L	1	10	\$ 275.00
10	REAR TAILGATE MECHANISM LOCK	L	1	10	\$ 339.00
11	REAR TAILGATE WEATHER STRIP	L	1	10	\$ 221.50
12	REAR BUMPER 1300	L	1	1000	\$ 1,837.50
13	REAR BUMPER SIDE RETAINER L/R	L	1	10	\$ 321.77
14	REAR BUMPER REVERSE SENSOR 225	L	1	CM	\$ 297.50
15	REAR BUMPER REVERSE SENSOR HOLDER	L	1	10	\$ 38.00
16	REAR BUMPER REVERSE SENSOR 'O' RING	L	1	100	\$ 22.00
17	REAR BUMPER REFLECTOR L/R	L	2	10	\$ 178.50
18	REAR BUMPER TOW HOOK COVER	L	1	10	\$ 132.70
19	REAR BUMPER REINFORCEMENT	L	1	2	\$ 834.27
20	REAR END PANEL	L	1	2	\$ 1,087.50
21	REAR END PANEL INNER TOP GARNISH	L	1	10	\$ 339.28

Subtotal before discount:

\$ 10,143.41

Percentage discount 5%: 10%

\$ 507.17

Sub-total 1

\$ 9,636.24

22	REAR TAILGATE WINDSCREE SEALANT	S	1	\$ 80.00	\$ 80.00
23	REAR TAILGATE NUMBER PLATE	S	1	\$ 25.00	\$ 25.00
24	REAR TAILGATE NUMBER PLATE FRAME	S	1	\$ 50.00	\$ 50.00
25	REAR TAILGATE INNER TRIM BOARD CLIPS - SET	S	1	\$ 50.00	\$ 50.00
26	REAR BUMPER CLIPS - SET	S	1	\$ 50.00	\$ 50.00
27	REAR END PANEL INNER TOP GARNISH CLIPS - SET	S	1	\$ 30.00	\$ 30.00

Subtotal before discount:

\$ 285.00

Percentage discount 0%:

0.00

Sub-total 2

\$ 285.00

Parts-total

\$ 9,921.24

LABOUR

1	To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	\$ 80.00
2	To remove, reinstall tailgate windscreen	\$ 150.00
3	To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	\$ 80.00
4	To remove, reinstall tailgate mechanism and check for function	\$ 80.00
5	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident	\$ 1,000.00
6	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	\$ 1,000.00
7	To apply anti-rust chemical on repaired and replaced panel.	\$ 80.00
Labour total		\$ 2,470.00
Parts & Labour total		\$ 12,391.24

P-4628
100
416250
70
1120