



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2504295

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 08/07/2025  
Reference CD/CTI24120002/Aua3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SLX 6756U  
Insured Veh. SME 144M  
Claim No. SNM24D206309  
Policy No. DMPCSNW00043342402  
Accident Date 07/11/2024  
Inspection Date 20/11/2024

| Description         | Total         |
|---------------------|---------------|
| Survey Inspection   | 280.00        |
| Resurvey Inspection |               |
| Digital Photographs |               |
| Transportation      |               |
| <b>Subtotal</b>     | <b>280.00</b> |
| <b>GST (9%)</b>     | <b>25.20</b>  |
| <b>Grand Total</b>  | <b>305.20</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                              |                                                                                                                                        |                                                                                                      |                               |            |
|------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------|-------------------------------|------------|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909 |                                                                                                                                        |                                                                                                      | Ref: CD/CTI24120002/Aua3q2(N) |            |
|                                                                                                |                                                                                                                                        |                                                                                                      | Date: 08/07/2025              |            |
|                                                                                                |                                                                                                                                        |                                                                                                      | Code: CTI                     |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                              |                                                                                                                                        |                                                                                                      |                               |            |
|                                                                                                | Insured Veh.                                                                                                                           | SME 144M                                                                                             | Veh. Inspected                | SLX 6756U  |
|                                                                                                | Policy No.                                                                                                                             | DMPCSNW00043342402                                                                                   | Coverage (\$)                 | 0.00       |
|                                                                                                | Claim No.                                                                                                                              | SNM24D206309                                                                                         | Excess (\$)                   | 0.00       |
|                                                                                                | Assign From                                                                                                                            |                                                                                                      | Assign Date                   | 20/11/2024 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                  |                                                                                                                                        |                                                                                                      |                               |            |
|                                                                                                | Make & Model                                                                                                                           | HYUNDAI ELANTRA                                                                                      | c.c                           | 1591       |
|                                                                                                | Engine No.                                                                                                                             | HIDDEN                                                                                               | Year of Reg.                  | 2018       |
|                                                                                                | Chassis No.                                                                                                                            | KMHD841CMJU660359                                                                                    | Colour                        | GREY       |
|                                                                                                | Odometer                                                                                                                               | 151619 KM                                                                                            | Steering                      | IN ORDER   |
|                                                                                                | Brakes                                                                                                                                 | IN ORDER                                                                                             | Modification                  | SPORTS RIM |
|                                                                                                | General                                                                                                                                | GOOD                                                                                                 |                               |            |
| <b>3. Conditions of Tyres</b>                                                                  |                                                                                                                                        |                                                                                                      |                               |            |
|                                                                                                |                                                                                                                                        | Size                                                                                                 | Make                          | Balance    |
|                                                                                                | R/H Front Tyre                                                                                                                         | 225/40 R18                                                                                           | GOODYEAR                      | 6 mm       |
|                                                                                                | L/H Front Tyre                                                                                                                         | 225/40 R18                                                                                           | GOODYEAR                      | 6 mm       |
|                                                                                                | R/H Rear Tyre                                                                                                                          | 225/40 R18                                                                                           | GOODYEAR                      | 6 mm       |
|                                                                                                | L/H Rear Tyre                                                                                                                          | 225/40 R18                                                                                           | GOODYEAR                      | 6 mm       |
| <b>4. Description of Damages</b>                                                               |                                                                                                                                        |                                                                                                      |                               |            |
|                                                                                                | THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.<br><br>DAMAGES SEE DETAILS.                                                             |                                                                                                      |                               |            |
| <b>5. General Information</b>                                                                  |                                                                                                                                        |                                                                                                      |                               |            |
|                                                                                                | Accident Date                                                                                                                          | 07/11/2024                                                                                           | Inspection Date               | 20/11/2024 |
|                                                                                                | Survey held at                                                                                                                         | HD PERFECT AUTOWORK PTE LTD<br>8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875 |                               |            |
| <b>5a. Remarks</b>                                                                             |                                                                                                                                        |                                                                                                      |                               |            |
|                                                                                                | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                      |                               |            |
| <b>5b. Estimate Days of Repair</b>                                                             |                                                                                                                                        |                                                                                                      |                               |            |
|                                                                                                | ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                                      | 4 Working Days                |            |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 6756U

| Qty                                | Description of Parts                         | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|----------------------------------------------|----------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |                                              |                      |                           |                   |
| 1                                  | REAR BUMPER                                  | TORN                 | 670.40                    | 475.00            |
| 1                                  | REAR BUMPER REFLECTOR LH                     | CRACKED              | 35.20                     | 35.20             |
| 1                                  | REAR BUMPER LOWER LIP                        | NOT NECESSARY        | 250.10                    | -                 |
| 2                                  | REAR BUMPER RETAINER @\$44.30                | N/S CRACKED          | 88.60                     | 44.30             |
| 1                                  | REAR BUMPER INNER GARNISH LH                 | NOT NECESSARY        | 137.50                    | -                 |
| 1                                  | TAILLAMP LH                                  | CRACKED              | 876.80                    | 876.80            |
| 1                                  | REAR FENDER LH                               | TO REPAIR SEE LABOUR | 1,890.50                  | -                 |
| 1                                  | REAR FENDER AIR VENT LH                      | DEFORMED             | 107.40                    | 107.40            |
| 1                                  | REAR FENDER COWLING LH                       | TORN                 | 146.80                    | 146.80            |
| 1                                  | REAR WINDSCREEN MOULDING                     | NOT NECESSARY        | 186.30                    | -                 |
| 1                                  | REAR AXLE                                    | NOT NECESSARY        | 2,140.00                  | -                 |
| 1                                  | REAR SHOCK ABSORBER RH                       | NOT NECESSARY        | 475.00                    | -                 |
| 1                                  | REAR WHEEL HUP WITH BEARING RH               | NOT NECESSARY        | 525.00                    | -                 |
|                                    | LESS 20% DISCOUNT                            |                      | -1,505.92                 | -337.10           |
|                                    |                                              |                      | 6,023.68                  | 1,348.40          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |                                              |                      |                           |                   |
| 1                                  | SET REAR BUMPER CLIP (SN)                    | NECESSARY            | 50.00                     | 30.00             |
| 1                                  | SET REAR BUMPER INNER GARNISH CLIP RH (SN)   | NOT NECESSARY        | 50.00                     | -                 |
| 1                                  | SET REAR BUMPER DIFFUSER (SPECAIL TYPE) (SN) | CRACKED              | 1,200.00                  | 700.00            |
| 1                                  | SET TAIL LAMP CLIP (SN)                      | NOT NECESSARY        | 30.00                     | -                 |
| 1                                  | REAR FENDER RH SEALANT (SN)                  | NOT NECESSARY        | 80.00                     | -                 |
| 1                                  | SET REAR FENDER INNER COWLING RH CLIP (SN)   | NECESSARY            | 50.00                     | 30.00             |
| 1                                  | SET REAR FENDER INNER TRIM RH CLIPS (SN)     | NOT NECESSARY        | 50.00                     | -                 |
| 1                                  | REAR WINDSCREEN SEALANT (SN)                 | NOT NECESSARY        | 80.00                     | -                 |
| 1                                  | REAR SPORT RIM (SN)                          | CUT                  | 1,000.00                  | 400.00            |
| 1                                  | REAR TYRE (SN)                               | NOT NECESSARY        | 480.00                    | -                 |
| 1                                  | BRAKE OIL (SN)                               | NOT NECESSARY        | 80.00                     | -                 |
| 1                                  | REAR WINDSCREEN INNER SEAL (SN)              | NOT NECESSARY        | 60.00                     | -                 |
|                                    |                                              |                      | 3,210.00                  | 1,160.00          |

Report Ref No. CD/CTI24120002/Aua3q2(N)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts                                                                            | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|     | <b><u>LABOUR</u></b>                                                                            |               |                           |                   |
|     | PANEL BEATING ,REMOVING AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER LH .         |               | 2,000.00                  | 300.00            |
|     | SPRAY PAINTING TO AFFECTED AREA .                                                               |               | 1,800.00                  | 800.00            |
|     | TUFF COAT.                                                                                      |               | 250.00                    | 40.00             |
|     | WIRING CHECK.                                                                                   |               | 250.00                    | 30.00             |
|     | REMOVE AND REFIX UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR.                              | NOT NECESSARY | 350.00                    | -                 |
|     | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING .                                          |               | 80.00                     | 50.00             |
|     | CONDUCT WATER LEAKAGE TEST.                                                                     | NOT NECESSARY | 80.00                     | -                 |
|     | REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT.                                    | NOT NECESSARY | 120.00                    | -                 |
|     | REMOVE AND REFIX REAR WINDSCREEN.                                                               | NOT NECESSARY | 120.00                    | -                 |
|     | REMOVE AND REFIX REAR UNDERCARRIAGE.                                                            | NOT NECESSARY | 650.00                    | -                 |
|     | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC. | NOT NECESSARY | 350.00                    | -                 |
|     |                                                                                                 |               | 6,050.00                  | 1,220.00          |
|     | <b>GRAND TOTAL</b>                                                                              |               | <b>15,283.68</b>          | <b>3,728.40</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>                     |               |                           | <b>2,950.00</b>   |

Report Ref No. CD/CTI24120002/Aua3q2(N)

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

**PHOTOGRAPHS FOR VEHICLE NO. : SLX 6756U**





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

INSPECTION PHOTOS (Page 2 of 8)

### PHOTOGRAPHS FOR VEHICLE NO. : SLX 6756U





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

INSPECTION PHOTOS (Page 3 of 8)

### PHOTOGRAPHS FOR VEHICLE NO. : SLX 6756U





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

INSPECTION PHOTOS (Page 4 of 8)


### PHOTOGRAPHS FOR VEHICLE NO. : SLX 6756U



**PHOTOGRAPHS FOR VEHICLE NO. : SLX 6756U**



**PHOTOGRAPHS FOR VEHICLE NO. : SLX 6756U**



**PHOTOGRAPHS FOR VEHICLE NO. : SLX 6756U**





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

**INSPECTION PHOTOS (Page 8 of 8)**

### PHOTOGRAPHS FOR VEHICLE NO. : SLX 6756U



**PHOTOGRAPHS FOR VEHICLE NO. : SLX 6756U**



**PHOTOGRAPHS FOR VEHICLE NO. : SLX 6756U**



**PHOTOGRAPHS FOR VEHICLE NO. : SLX 6756U**



**PHOTOGRAPHS FOR VEHICLE NO. : SLX 6756U**



**PHOTOGRAPHS FOR VEHICLE NO. : SLX 6756U**



**PHOTOGRAPHS FOR VEHICLE NO. : SLX 6756U**



**PHOTOGRAPHS FOR VEHICLE NO. : SLX 6756U**



**PHOTOGRAPHS FOR VEHICLE NO. : SLX 6756U**

