



 enquiry@sh-motor.com

160 Sin Ming Drive
#07-02 Sin Ming AutoCity
Singapore 575722

Co. Reg. No. : 198701322K
GST Reg. No.: M2-0076269-0

29/11/2024

Estimated cost of repair for vehicle no:		GX5858A		BYD ET3			
Accident involving vehicle no:		GX5858A		&		GBK9476U On 15/11/2024	
Description	Quantity	Cost	Price				
Rear bumper 1050	1	\$	1,170.00				
Rear bumper outer side retainer @\$45.50	2	\$	91.00				
Rear bumper inner side retainer @\$51.00	2	\$	102.00				
Rear bumper 3rd brake lamp	1	\$	380.00				
Rear bumper reverse sensor @\$195.00	2	\$	390.00				
Tail gate 3400	1	\$	4,200.00				
Tailgate lock	1	\$	199.00				
Tail gate weather strip	1	\$	244.00				
Tail gate outer chrome garnish	1	\$	420.00				
Tail gate "BYD Logo" emblem	1	\$	110.50				
Tail gate "T3" emblem	1	\$	40.00				
Tail gate inner trim board	1	\$	425.80				
Rear end panel	1	\$	550.00				
Car plate lamp @\$72.00	2	\$	144.00				
		\$	8,466.30				
		\$	846.63				
		\$	9,312.93				
Special Nett Rear inner trim board clip Rear camera Rear end panel sealant				set 1 1	\$	30.00 400.00 40.00	
Labour To dismantle, replace, cut, weld, knock out dents to straighten accident damaged parts. Transfer of existing tailgate mechanism to new tailgate Remove & refix tailgate windscreen glass Remove & refix/replace rear bumper reverse sensor & conduct distance safety setting Remove & refix/replace rear reverse camera & conduct distance safety setting Wiring /bulb checking/focusing To putty & spray paint accident damaged parts and adjacent panels					\$	600.00 90.00 120.00 90.00 70.00 40.00 700.00	
					\$	11,492.93	