

ASS. REC. BY:

REF:

CTZ

CS/CT124120008/Knh3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

04/29

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKP 9122H

Yr Regn:

10, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Altis

c.c

1598

Colour

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

114646

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NR053REH104518310

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Yoko 205/55R16

R: Windforce

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

9

mm

L/Bal.

8

mm

L/Bal.

9

mm

D.O.A.

28/11/24

D.O.I.

3/12/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/12 21 Rpt & 3350h Canbu (Red, \$ 13951.55, 80%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS, SI

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 02-12-2024
VEHICLE : SKP 9122 H
MAKE/MODEL : TOYOTA / ALTIS
CHASSIS NO : MR053REH104518310
MILEAGE :
TYRE SIZE :
DOA : 28-11-2024
TP INSURANCE : CHINA TAIPING

Not Withheld
11 Lyr @ 335dp
Penny After Rain
5 days

List items

01 PC	FRONT DOOR (RH)	1358	At/wap	\$ 1,929.80	✓
01 PC	FRONT DOOR INNER LOCK (RH)			\$ 494.96	X
01 PC	FRONT DOOR CATCH LOCK (RH)			\$ 95.30	X
01 PC	FRONT DOOR POWER WINDOW REGULATOR (RH)			\$ 385.04	X
01 PC	FRONT DOOR POWER WINDOW MOTOR (RH)			\$ 795.72	X
01 PC	FRONT DOOR WEATHERSTRIP (RH)			\$ 239.57	X
01 PC	FRONT DOOR INNER TRIM BOARD (RH)			\$ 758.74	X
01 PC	REAR DOOR CENTRE BODY PILLAR PANEL			\$ 603.76	X
01 PC	REAR DOOR (RH)	1250	At/wap	\$ 1,844.32	✓
01 PC	REAR DOOR POWER WINDOW REGULATOR (RH)			\$ 378.40	X
01 PC	REAR DOOR POWER WINDOW MOTOR (RH)			\$ 774.83	X
01 PC	REAR DOOR WEATHERSTRIP (RH)			\$ 239.57	X
01 PC	REAR DOOR INNER TRIM BOARD (RH)			\$ 739.57	X
01 PC	REAR DOOR CHECKER (RH)			\$ 138.25	X
02 PCS	REAR DOOR HINGER (RH)		2 X \$95.68	\$ 191.36	X
01 PC	REAR FENDER (RH)			\$ 1,957.72	X
01 PC	REAR BUMPER	702.60	my	\$ 1,157.28	✓
01 PC	REAR BUMPER RETAINER (RH)			\$ 177.36	X
256				<u>\$ 12,901.55</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Special Nett Item:

01 PC	FRONT DOOR STICKER (RH)	nn \$	45.00	—
01 PC	REAR DOOR STICKER (RH)	nn \$	45.00	—
01 PC	WINDSCREEN SEALANT	\$ nn	80.00	X
01 PC	PANEL SEALANT	\$ nn	80.00	X
				\$ 250.00

Labour:

<u>Labour:</u>			
1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$	1,800.00	8001
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA	\$	1,500.00	
3. TO SUPPLY LABOUR & REFIT WINDSCREEN	nn \$	250.00	x
4. TO SUPPLY LABOUR TO REMOVE & REFIT UPHOSTLER FOR REPAIR	\$	400.00	801
5. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL	\$	200.00	601
		\$ 4,150.00	

TOTAL PARTS

\$ 12,901.55

SPECIAL NETT ITEM

\$ 250.00

TOTAL LABOUR

\$ 4,150.00

TOTAL COST OF REPAIR

\$ 17,301.55
