

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0894/2024/EQ
DATE : 30-Nov-24
WIP : 40305

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 3/12/2024

YOUR INSURED VEH NO : SJW 1515 K

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MS SOH PING XIAN JENNY
ADDRESS : 21 SAMPAN PLACE
#08-04
SINGAPORE 436593
TELEPHONE : HP +65 91996969
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800002867-05
VEHICLE NO : SGT 77 R
MODEL CODE : AUDI Q7 2.0 TFSI QU
MODEL YEAR : 15/1/2018
ENGINE NO : CYR 047035
CHASSIS NO : WAUZZZ4M1JD004127
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Nov-24
PLACE OF ACCIDENT : "UBPOINT" CARPARK. 61 UBI AVE 1, SG408941. CARPARK
OF THE BUILDING BASEMENT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGT 77 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00	/
2	TO REMOVE AND TRANSFER LHS FRONT AND REAR DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 900.00	/
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$ 1,800.00	X
4	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOFLINER AND DISENGAGE CURTAIN AIRBAGETC.	S/N \$ 1,800.00	X
5	TO REMOVE AND REINSTALL REAR BUMPER. TO DISMANTLE AND RENEW LHS FRONT AND REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 8,100.00 <i>\$100 x 3</i>	1500
6	TO RESPRAY LHS FRONT AND REAR DOOR, LHS REAR FENDER, REAR END PANELLING, LHS SILL PANEL, ROOF CHANNEL, DOOR ENTRANCE, DRAIN CHANNEL, LHS FRONT AND REAR DOOR LOWER COVER, LHS REAR DOOR WHEEL ARCH TRIM, BOTH REAR WHEEL ARCH TRIMS AND LHS FRONT AND REAR DOOR HANDLE.	\$ 8,700.00 <i>150 x 3 = 450</i>	3150
150	<i>Rear Bumper lower</i>		
SUBTOTAL LABOUR CHARGES		: \$ 21,660.00	


55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGT 77 R

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RENEW LHS 1/4 GLASS AND CARRY OUT WATER SEEPAGE TEST	S/N \$	500.00	X
8	TO INSTALL SOLAR FILM FOR LHS 1/4 GLASS.	S/N \$	400.00	X
9	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	/
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	/
TOTAL LABOUR CHARGES		:	\$ 23,132.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGT 77 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - LH / 	1	\$ 6,166.00 / \$4,932.80	
2	FRONT DOOR OUTER SEAL - LH / 	1	\$ 315.00 / \$251.60	
3	BONDING AGENT / 	1	\$ 54.00 / \$43.04	
4	CLEANING SOLUTION / 	1	\$ 92.00 / \$72.88	
5	APPLICATOR   x nn	1	\$ 10.00	
6	GROMMET  nn	8	\$ 26.00	
7	FRONT DOOR ATTACHMENT PARTS  nn	1	\$ 390.00	
8	FRONT DOOR COVER - LH (S/L) / 	1	\$ 823.00 / \$658.40	
9	FRONT DOOR CATCH - LH ? x nn	1	\$ 154.00	
10	FRONT DOOR EXTERIOR HANDLE - LH  nn	1	\$ 460.00	
11	FRONT DOOR EXTERIOR HANDLE UNDERLAY - LH FRONT	1	\$  nn 7.00	
12	FRONT DOOR EXTERIOR HANDLE UNDERLAY - LH REAR	1	\$  nn 8.00	
13	REAR DOOR - LH / 	1	\$ 6,441.00 / \$5,152.80	
14	REAR DOOR OUTER SEAL / 	1	\$ 312.00 / \$249.20	
15	BONDING AGENT  ? x nn	1	\$ 54.00	
16	CLEANING SOLUTION ? x nn	1	\$ 92.00	
17	APPLICATOR ? x nn	1	\$ 10.00	
18	GROMMET ? x nn	7	\$ 23.00	
19	REAR OUTER DOOR SEAL - LH / 	1	\$ 238.00 / \$190.00	
20	REAR DOOR CATCH - LH ? x nn	1	\$ 154.00	
SUB TOTAL SPARE PARTS		:	\$ 15,829.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGT 77 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR DOOR COVER - LH (S/L) / CV	1	\$ 983.00	/ \$786.40
22	REAR DOOR WHEEL COVER - LH / n/c (photo)	1	\$ 232.00	/ \$185.20
23	REAR SIDE PANEL - LH X nn	1	\$ 8,973.00	
24	REAR SILL PANEL SEAL - LH X nn	1	\$ 315.00	
25	REAR QUARTER GLASS X nn	1	\$ 1,190.00	
26	WINDOW PRIMER X nn	1	\$ 27.00	
27	REAR WHEEL ARCH COVER - LH / RH / na (photo)	2	\$ 1,010.00	/ \$807.20
28	REAR ALUMINIUM RIM - LH / 14 x R	1	\$ 2,544.00	/ \$2,035.20
29	REAR ALUMINIUM RIM RUBBER VALVE / 14 x nn	1	\$ 5.00	
30	1/4 GLASS SEALANT X nn	S/N	\$ 100.00	
31	METAL FILTER POWDER X nn	S/N	\$ 280.00	
32	ACRYLIC SEALANT X nn	S/N	\$ 180.00	
33	STONE CHIP X nn	S/N	\$ 180.00	
34	CAVITY WAX X nn	S/N	\$ 140.00	
35	SUNDRIES / x nn		\$ 1,000.00	
TOTAL SPARE PARTS		:	\$ 32,988.00	\$15,364.72
TOTAL LABOUR CHARGES		:	\$ 23,132.00	\$6,482.00
GRAND TOTAL		:	\$ 56,120.00	\$21,846.72

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Steve (LKK)
3/12/24, 10.10 am
m R
P/P

By Bel sy, 7 days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT