

ONE GARAGE PTE LTD

8 KAKI BUKIT AVENUE 4 #03-33 PREMIER@KAKI BUKIT

SINGAPORE 415875

TEL: 96311088

TO	: NTUC	DATE	: 4/12/2024
VEHICLE NO	: SNS7222P (2014)	<i>Hui Rong</i>	
VEHICLE MODEL	: MERCEDES BENZ C180		
CHASSIS NO	: WDD2050402R003673		

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>		5341 4806.90	1461.00	✓
1	FRONT BUMPER <i>torn</i>		98.00	✓
2	FRONT BUMPER SIDE HOLDER <i>crack</i>		265.00	+
3	FRONT BUMPER SENSOR <i>new</i>		1012.00	+
4	FRONT FENDER <i>Repair</i>		221.00	+
5	FRONT FENDER INNER SHIELD <i>new</i>		3782.00	✓
6	HEADLAMP <i>ut</i>		295.00	+
7	FRONT STAY ARM		471.50	+
8	FRONT LOWER ARM		487.80	+
9	FRONT KNUCKLE ARM		385.20	+
10	FRONT SHOCK ABSORBER		286.00	+
11	FRONT CONTROL ARM		314.40	+
12	FRONT WHEEL HUB C/W BEARING		9078.90	
		Less 10%	907.89	10%
			8171.01	
<u>SPECIAL NETT ITEMS</u>		30	30.00	✓
1	FRONT BUMPER CLIPS <i>new</i>		30.00	+
2	FRONT FENDER INNER SHIELD CLIPS <i>new</i>		1250.00	+
3	FRONT WHEEL RIM <i>new</i>		280.00	+
4	FRONT TYRE <i>new</i>			
Total Parts			1590.00	

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR ASSESSMENT (S\$)
<u>LABOUR</u>			
1	PANEL BEATING	800.00	300
2	SPRAY PAINTING	300.00	400
3	WIRING	50.00	30
4	TO APPLY TUFF COAT	150.00	30
5	TO DISMANTLE FRONT UNDERCARRIAGE	350.00	+
6	TO PERFORM DIAGNOSTIC TEST	250.00	+
7	TO PERFORM WHEEL ALIGNMENT	150.00	+
Labour Total :		2550.00	

760

total: 5596.90

H/s : H.H.K. ✓

03 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: