

HUAT AUTOMOBILE AIR CON SERVICE

BLK 3007 Ubi Road 1 #01-404
Singapore 408701 Tel 67461868 Fax 67462065

Not Authorized
on
3/12/24
1/5 4800
4 days
unphoto Hhering

VEHICLE No: GBJ 4649B

1PC	FRONT BUMPER	<i>DIS</i>	\$721.30	✓
1PC	FRONT BUMPER SIDE BRACKET N/S	<i>CNE</i>	\$145.50	✓
1PC	FRONT BUMPER SIDE GRILLE N/S	<i>11</i>	\$122.80	X
1PC	HEADLAMP N/S	<i>CNE</i>	\$1,390.10	✓
1PC	FRONT GRILLE ASSY	<i>CNE</i>	\$645.20	✓
1PC	FRONT CORNER PANEL N/S	<i>beat/3wc</i>	\$422.10	✓
1PC	FRONT DOOR VIEW MIRROR N/S	<i>un</i>	\$485.20	X
1PC	FRONT DOOR N/S	<i>DD/beat</i>	\$2,655.30	✓
1PC	FRONT DOOR OUTER PILLAR N/S	<i>R</i>	\$899.10	X
1PC	FRONT STEP PANEL GARNISH N/S	<i>cut/Re</i>	\$211.80	✓
1PC	FRONT STEP PANEL N/S	<i>R</i>	\$245.60	X
			\$7,944.00	
LESS 25%			\$5,958.00	

S.NETT ITEM

1SET	FRONT BUMPER CLIPS	<i>Re</i>	\$40.00	30 S/N
1SET	FRONT DOOR 'ROC' STICKER N/S	<i>Re</i>	\$35.00	✓ S/N

TO CHECK WIRING	\$50.00	20
TO SPRAY RUST PROOFING	\$80.00	30
TO DISMANTLE & REFIX FRONT WINDSCREEN	\$100.00	X
TO DISMANTLE & REFIX FRONT DOOR MECHANISM	\$80.00	50
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$880.00	400
TO PUTTY & SPRAY PAINTING	\$900.00	800
TOTAL	\$8,123.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) to the surveyor
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-6191-3
252
4643.48
65
1300
6008.48
282
4806