

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 4649B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DISTORTED	721.30	721.30
1	FRONT BUMPER SIDE BRACKET N/S	CRACKED	145.50	145.50
1	FRONT BUMPER SIDE GRILLE N/S	NOT NECESSARY	122.80	-
1	HEADLAMP N/S	CRACKED	1,390.10	1,390.10
1	FRONT GRILLE ASSY	CRACKED	645.20	645.20
1	FRONT CORNER PANEL N/S	BENT/BUCKLED	422.10	422.10
1	FRONT DOOR VIEW MIRROR N/S	NOT NECESSARY	485.20	-
1	FRONT DOOR N/S	DENTED/BENT	2,655.30	2,655.30
1	FRONT DOOR OUTER PILLAR N/S	TO REPAIR SEE LABOUR	899.10	-
1	FRONT STEP PANEL GARNISH N/S	CUT/DEFORMED	211.80	211.80
1	FRONT STEP PANEL N/S	TO REPAIR SEE LABOUR	245.60	-
	LESS 25% DISCOUNT		-1,986.00	-1,547.82
			5,958.00	4,643.48
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	40.00	30.00
1	SET FRONT DOOR 'ROC' STICKER N/S (SN)	NECESSARY	35.00	35.00
			75.00	65.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.		80.00	30.00
	TO DISMANTLE & REFIX FRONT WINDSCREEN.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX FRONT DOOR MECHANISM.		80.00	50.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR OUTER PILLAR N/S AND FRONT STEP PANEL N/S.		880.00	400.00
	TO PUTTY & SPRAY PAINTING.		900.00	800.00
			2,090.00	1,300.00
	GRAND TOTAL		8,123.00	6,008.48

Report Ref No. CS/INC24120012/Uvh3m4(N)



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,800.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. CS/INC24120012/Uvh3m4(N)

TOTAL FOR SPARE PARTS: \$ 6,033.00 \$ 4,708.48 TOTAL FOR LABOUR: \$ 2,090.00 \$ 1,300.00 TOTAL REPAIR COST: \$ 8,123.00 \$ 6,008.48

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser