

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 02.12.2024

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SKR93G**
MODEL : **MERCEDES S500**
DATE OF ACCIDENT : 21.11.2024
TIME OF ACCIDENT : 15:10 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>behind</i>	1	\$ 3,525.00	\$ 3,525.00
2	REAR BUMPER TOWING COVER	1	\$ 86.50	\$ 86.50
3	REAR BUMPER CORNER BRACKET	2	\$ 172.30	\$ 344.60
4	REAR BUMPER SIDE RETAINER	2	\$ 195.30	\$ 390.60
5	REAR BUMPER BRACKET (CENTER) <i>HP</i>	2	\$ 385.00	\$ 770.00
6	REVERSE SENSOR <i>th</i>	2	\$ 435.00	\$ 870.00
7	REVERSE SENSOR HOLDER	6	\$ 68.50	\$ 411.00
8	REVERSE SENSOR WIREHARNESS	1	\$ 698.30	\$ 698.30
9	TAILLAMP	2	\$ 1,468.00	\$ 2,936.00
10	REAR FENDER COWLING <i>see in</i>	2	\$ 342.71	\$ 685.42

TOTAL PRICE \$ 10,717.42
LESS 10% \$ 1,071.74
SUB TOTAL PRICE \$ 9,645.68

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER DIFFUSER (CARBON FIBER) <i>per</i>	1	\$ 2,800.00	\$ 2,800.00
4	REAR BUMPER CLIP (SET) <i>see</i>	1	\$ 80.00	\$ 80.00
6	TAILLAMP CLIP (SET) <i>see in</i>	1	\$ 80.00	\$ 80.00
7	REAR FENDER TOP GARNISH CLIP (SET) <i>see in</i>	1	\$ 80.00	\$ 80.00
8	REAR EXHAUST CHROME PIPE(SPECAIL TYPE) <i>see in</i>	1	\$ 1,200.00	\$ 1,200.00

TOTAL \$ 4,290.00

Local Price 500/ea

50

X

X

X

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SKR93G**
MODEL : **MERCEDES S500**
DATE OF ACCIDENT : 21.11.2024
TIME OF ACCIDENT : 15:10 HOURS

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,200.00	250
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	250
3	TUFF COAT	\$ 250.00	X
4	WIRING CHECK	\$ 150.00	X
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	X
6	TRANSFER BOOTLID MECHANISM	\$ 80.00	X
7	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X
8	REMOVE AND REFIX REAR REVERSE SENSOR	\$ 80.00	50
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 650.00	150

TOTAL \$ 3,760.00

TOTAL PARTS COST : \$ 13,935.68
TOTAL LABOUR COST : \$ 3,760.00
TOTAL REPAIR COST : \$ 17,695.68

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian G
L/S 03/12/24