



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 ATTN: CALEEN YIT			Ref: CS/AGI24120014/Avp3e2(N) Date: 11/03/2025 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SFZ 817C	Veh. Inspected	SGA 2789G
	Policy No.	P11081827R00	Coverage (\$)	0.00
	Claim No.	C10033178/CY	Excess (\$)	0.00
	Assign From	CALEEN YIT	Assign Date	02/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	HONDA ODYSSEY	c.c	2356
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JHMRC1890FC202421	Colour	SILVER
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55 R17	FORTUNE	6 mm
	L/H Front Tyre	215/55 R17	FORTUNE	6 mm
	R/H Rear Tyre	215/55 R17	FORTUNE	6 mm
	L/H Rear Tyre	215/55 R17	FORTUNE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/11/2024	Inspection Date	02/12/2024
	Survey held at	KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	