

2020 SPRAY PAINTING PTE LTD
8 KAKI BUKIT AVE 4
#03-19 PREMIER @KAKI BUKIT
SINGAPORE 415875

TO	: AUTO & GENERAL	DATE	: 3/12/2024
VEHICLE NO	: SBP6979D (1991)		
VEHICLE MODEL	: MERCEDES BENZ 200E		
CHASSIS NO	: WDB1240212B330817		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Repair</i>	1	\$ 1,620.00	\$ 1,620.00
2	REAR BUMPER PAD <i>cut</i>	1	\$ 439.00	\$ 439.00
3	REAR BUMPER TOP CHROME MOULDING	1	\$ 258.00	\$ 258.00
4	REAR BUMPER TOP SIDE CHROME MOULDING	2	\$ 221.00	\$ 442.00
5	REAR BUMPER SIDE HOLDER	2	\$ 86.00	\$ 172.00
6	REAR STAY ARM <i>new</i>	1	\$ 310.00	\$ 310.00
7	REAR CONTROL ARM <i>3 Bent</i>	1	\$ 345.00	\$ 345.00
8	REAR LOWER ARM	1	\$ 358.00	\$ 358.00
9	REAR KNUCKLE ARM <i>2nd</i>	1	\$ 898.00	\$ 898.00
10	REAR WHEEL HUB C/W BEARING <i>new</i>	1	\$ 315.00	\$ 315.00
11	REAR SHOCK ABSORBER <i>new</i>	1	\$ 287.00	\$ 287.00
12	FRONT DOOR WING MIRROR <i>Damaged</i>	1	\$ 1,750.00	\$ 1,750.00

TOTAL PRICE: \$ 7,194.00
 LESS 10% \$ 719.40
 SUB TOTAL PRICE: \$ 6,474.60

3027
 2724.30

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR WHEEL RIM <i>lit</i>	1	\$ 1,000.00	\$ 1,000.00
2	REAR TYRE <i>new</i>	1	\$ 280.00	\$ 280.00

TOTAL: \$ 1,280.00

650

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 500.00	300	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 400.00	300	
3	WIRING CHECK	\$ 150.00	X.	
4	TO REMOVE REVERSE SENSOR	\$ 100.00	X.	
5	TO REMOVE REAR UNDERCARRIAGE	\$ 380.00	200	
6	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	80	

TOTAL: \$ 1,680.00

880

ESTIMATE REPORT

TOTAL PARTS COST: \$ 7,754.60
TOTAL LABOUR COST: \$ 1,680.00
TOTAL REPAIR COST: \$ 9,434.60

total: 4254.30

L/s: 3.4K.

04 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: