

MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: NO:60 JALAN LAM HUAT CARROS CENTRE #05-68 S737869

HP: 98888885

Estimation

Date:

2/12/2024

Vehicle:

SN01151K

Make / Model:

HYUNDAI KONA

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR BUMPER (no paint) / CUT	1	\$ 1,258.00	\$ 1,258.00
2	REAR BUMPER SIDE RETAINER LH ? x nn	2	\$ 68.00	\$ 136.00
4	REAR BUMPER SIDE GARNISH TOP LH (not p-d) ?	1	\$ 321.00	\$ x nn 321.00
5	TAILAMP LH / BR	1	\$ 895.00	\$ 895.00
7	REAR FENDER WHEEL ARCH LH / CUT	1	\$ 678.00	\$ 678.00
				\$ 3,288.00
			Less 20%	\$ 657.60
			Total	\$ 2,630.40
S/Nett items:				
1	REAR FENDER WHEEL ARCH CLIPS / n/c	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CILP / n/c	1	\$ 50.00	\$ 50.00
3	REVERSE SENSOR X nn	1	\$ 220.00	\$ 220.00
				\$ 320.00
Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 150.00	\$ 150.00
2	REMOVE AND REFIX REAR REVERSE SENSOR	1	\$ 150.00	\$ 150.00
4	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 100.00	\$ 100.00
5	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 500.00	\$ 500.00
6	PANEL BEATING ON AFFECTED AREAS	1	\$ 500.00	\$ 500.00
				\$ 1,400.00
			Parts Replacement Amount	\$ 2,950.40
			Total Amount for Labour	\$ 1,400.00
			Total Amount	\$ 4,350.40

Steve (LKK)
2/12/24, 4.17pm
m
L/S
LJ AL LJ
2 days

2,360

L/S - 1,888
= 1900

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: