

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

Lonpac Insurance Bhd
 300 Beach Road #17-04/07
 The Concourse
 Singapore 199555
 Tel: 6250 7388
 Fax: 6296 2706

Xiao Chun.

DATE : 21.11.2022
 VEH NO : GBF9616J
 MODEL : Nissan NV200
 D O A : 17.11.2022
 YR REF : Own Damage

QUOTATION

Attn : Motor Claims Dept

RE : ESTIMATE FOR ACCIDENT REPAIR GBF9616J (NISSAN NV200)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
1	Front Fender - RH <i>Dented.</i>	1	215.00 ✓
2	Front Fender Side Lamp - RH <i>ut</i>	1	28.00 ✓
3	Front Fender Inner Panel - RH <i>Repair</i>	1	550.00 x
4	Front Fender Inner Shield - RH <i>Deformed</i>	1	78.00 ✓
5	Front Fender Inner Shield Clips - RH <i>new</i>	1	10.00 ✓
6	Front Door - RH <i>Distorted</i>	1	635.00 ✓
7	Front Door Glass Outer Moulding - RH <i>new</i>	1	65.00 x
8	Front Door Lock - RH <i>new</i>	1	115.00 ✓
9	Front Door Weatherstripe - RH <i>new</i>	1	55.00 x
10	Front Door Hinges - RH (Upper / Lower) <i>Best</i>	2	80.00 ✓
11	Front Door Checker - RH <i>new</i>	1	38.00 ✓
12	Front Door Glass Regulator - RH <i>new</i>	1	65.00 ✓
13	Front Door Glass Regulator Motor - RH <i>new</i>	1	245.00 x
14	Front Door Inner Trim Board <i>new</i>	1	420.00 x
15	Front Door Inner Trim Board Clips <i>new</i>	1	20.00 x
16	Front Door Handle <i>new</i>	1	240.00 x
17	Front Door Wing Mirror <i>Distorted</i>	1	480.00 ✓
18	Centre Pillar - RH <i>Repair</i>	1	910.00 x
19	Fuel Tank Cap <i>Repair</i>	1	35.00 x
20	Rocker Panel - RH <i>Dented.</i>	1	780.00 x
21	Sliding Door - RH <i>Dented.</i>	1	660.00 ✓
22	Sliding Door Lock - RH <i>new</i>	1	118.00 x
23	Sliding Door Weatherstripe - RH <i>new</i>	1	68.00 x
24	Sliding Door Hinges - RH (Upper) <i>new</i>	1	42.00 x
25	Sliding Door Hinges - RH (Lower)	1	85.00 x
26	Sliding Door Roller Central - RH <i>new</i>	1	78.00 x
27	Rear Fender - RH <i>Distorted</i>	1	855.00 ✓
28	Rear Fender Inner Panel - RH <i>Repair</i>	1	680.00 x
29	Rear Fender Railing - RH <i>Dented.</i>	1	350.00 ✓
30	Tail Lamp - RH <i>crushed.</i>	1	118.00 ✓

510.

RE : ESTIMATE FOR ACCIDENT REPAIR GBF9616J (NISSAN NV200)

31	Tail Lamp Panel - RH <i>Repair</i>	1	275.00 <i>✓</i>
32	Rear Bumper <i>Rebound</i>	1	335.00 <i>✓</i>
33	Rear Bumper Clips <i>new</i>	1	10.00 <i>✓</i>
34	Rear Bumper Bracket - RH <i>end</i>	1	90.00 <i>✓</i>
35	Rear Wheel Cap - RH <i>cut</i>	1	95.00 <i>✓</i>
36	Rear Suspension - RH <i>3 new</i>	1	78.00 <i>+</i>
37	Rear Axle Beam - RH <i>new</i>	1	1,780.00 <i>+</i>
Sub Total			10,781.00
Add 15%			1,617.15
Total Parts			\$ 12,398.15

S/NETT ITEMS

1	Company Sticker <i>not to be insured</i>	2 sets	350.00 <i>+</i>
2	Company Address Sticker <i>new</i>	1	40.00 <i>30</i>
3	Rear Wheel Rim - RH <i>new</i>	1	280.00 <i>+</i>
4	Rear Tyre - RH <i>cut</i>	1	160.00 <i>120</i>
			830.00
Total Parts			\$ 13,228.15

Labour Charge:

1	To knocking & pull out RH side portion and renew above parts	\$ 1,800.00 <i>1200</i>
2	To putty and spray up paint work	\$ 1,600.00 <i>1100</i>
3	To check wiring system	\$ 100.00 <i>30</i>
4	To spray tuffcoat	\$ 150.00 <i>120</i>
5	To transfer front door fittings	\$ 150.00 <i>80</i>
6	To transfer sliding door fittings	\$ 150.00 <i>80</i>
7	To remove reverse sensor	\$ 100.00 <i>50</i>
8	To remove rear undercarriage	\$ 380.00 <i>+</i>
9	To perform wheel alignment	\$ 150.00 <i>80</i>
		\$ 4,580.00

Grand Total \$ 17,808.15

total: 8372.05
 L/S: G.71C.

Adrian Lij
 r/s 22/11/22
 10 Days *new*
 Excess \$500 *Authorised.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

GST Will be reflected in the final bill

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: