

Date: 29/03/2022

Vehicle No: SNB9906B

Model: TESLA MODEL 3 STANDARD RANGE

Chassis: LRW3F7FJ5MC282819

Reg.Year: 2021

Third Party Insurer: AIG

Third Party Veh No: YL135K

Date of Accident: 28/03/2022

Estimator: KIT

Surveyor:

*Not authorized
Recovery B4 pain*

21 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID	1		Bt \$728.97
2	REAR BOOTLID "TESLA" EMBLEM	1		Re \$37.38
3	REAR BOOTLID LAMP RH	1		Bt \$177.57
4	REAR BOOTLID OUTER SWITCH HANDLE	1		\$121.50
5	REAR BOOTLID MECHANISM LOCK	1		Tu \$54.21
6	REAR BOOTLID LOCK STRIKER	1		\$52.34
7	REAR BOOTLID INNER TRIM BOARD	1		\$345.79
8	REAR BOOTLID HINGE LH	1		Oil \$61.68
9	REAR BOOTLID HINGE RH	1		Rt \$61.68
10	REAR BOOTLID STRUT LH	1		\$93.46
11	REAR BOOTLID STRUT RH	1		\$93.46
12	REAR TAIL LAMP RH	1		Bt \$280.37
13	REAR TAIL LAMP BRACKET RH	1		Re \$2.80
14	REAR TAIL LAMP REFELCTOR RH	1		mi \$36.45
15	REAR BUMPER	1		Bt/cm \$663.55
16	REAR BUMPER SIDE BRACKET RH	1		CR \$7.48
17	REAR BUMPER CENTER BRACKET	1		\$52.34
18	REAR BUMPER LOWER LIP	1		Pe \$140.19
19	REAR BUMPER UNDER COVER	1		Pe \$205.61
20	REAR BUMPER REFLECTOR RH	1		CR \$20.56
21	REAR BUMPER PARKING SENSOR	2	\$158.88	short \$476.64
22	REAR BUMPER PARKING SENSOR BRACKET	2	\$4.67	Re \$14.01
23	REAR BUMPER REINFORCEMENT	1		\$271.03
24	REAR END PANEL	1		Rt \$448.60
25	REAR END PANEL TOP GARNISH	1		\$299.07
26	REAR FENDER RH	1		Bt \$1,242.99
27	REAR FENDER QUARTER GLASS RH	1		Re \$280.37
28	REAR FENDER INNER SHIELD RH	1		Reform \$116.82
29	REAR FENDER INNER PANEL RH	1		\$962.62
30	REAR FENDER INNER PANEL EXTENSION RH	1		\$112.15
31	REAR FENDER INNER AIR VENT RH	1		Re \$14.95
32	REAR WINDSCREEN GLASS	1		CR \$644.86
33	REAR WINDSCREEN TOP MOULDING	1		Re \$88.79
34	REAR WINDSCREEN BOTTOM MOULDING	1		Re \$65.42
35	FRONT BONNET	1		Bt \$663.55
36	FRONT BONNET HINGE LH	1		\$74.77

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 29/03/2022
 Vehicle No: SNB9906B
 Model: TESLA MODEL 3 STANDARD RANGE
 Chassis: LRW3F7FJ5MC282819
 Reg.Year: 2021

Third Party Insurer: AIG
 Third Party Veh No: YL135K
 Date of Accident: 28/03/2022
 Estimator: KIT
 Surveyor:

37	FRONT BONNET HINGE RH	1		\$74.77	7
38	FRONT BONNET STRUT LH	1		Sn \$52.34	X
39	FRONT BONNET STRUT RH	1		Sn \$52.34	X
40	FRONT BONNET "TESLA" EMBLEM	1		M \$48.60	✓
41	FRONT BONNET LOCK	1		\$177.57	7
42	FRONT BONNET LOCK ACTUATOR ASSY	1		Sn \$107.48	X
43	FRONT BONNET STRIKER	1		R \$2.80	X
44	FRONT LUGGAGE COMPARTMENT	1		Dr \$64.49	—
45	FRONT LUGGAGE COMPARTMENT MAT	1		Dr \$74.77	—
46	FRONT HEADLAMP LH	1		Sn \$1,308.41	X
47	FRONT HEADLAMP RH	1		CM \$1,308.41	✓
48	FRONT HEADLAMP LOWER BRACKET LH	1		Sn \$7.48	X
49	FRONT HEADLAMP LOWER BRACKET RH	1		\$7.48	7
50	FRONT BUMPER	1		Tn \$663.55	✓
51	FRONT BUMPER SIDE BRACKET LH	1		Sn \$9.35	X
52	FRONT BUMPER SIDE RBACKET RH	1		\$9.35	7
53	FRONT BUMPER CENTER UPPER BRACKET LH	1		Sn \$12.15	X
54	FRONT BUMPER CENTER UPPER BRACKET RH	1		\$12.15	7
55	FRONT BUMPER LOWER GRILLE	1		Sn \$102.80	X
56	FRONT BUMPER REINFORCEMENT	1		R \$271.03	✓
57	FRONT BUMPER ABSORBER FOAM	1		CM \$46.73	✓
58	FRONT BUMPER REINFORCEMENT CRUSH CAN LH	1		Sn \$52.34	X
59	FRONT BUMPER REINFORCEMENT CRUSH CAN RH	1		\$52.34	7
60	FRONT BUMPER LOWER REINFORCEMENT	1		\$102.80	7
61	FRONT BUMPER LOWER REINFORCEMENT CRUSH CAN LH	1		Sn \$59.81	X
62	FRONT BUMPER LOWER REINFORCEMENT CRUSH CAN RH	1		\$59.81	7
63	FRONT SUPPORT BEAM	1		\$738.32	7
64	FRONT SUPPORT BEAM BRACKET LH	1		Sn \$7.48	X
65	FRONT SUPPORT BEAM BRACKET RH	1		\$7.48	7
66	FRONT BUMPER UNDER COVER	1		Sn \$186.92	X
67	FRONT BUMPER PARKING SENSOR	6	\$158.88	\$953.28	7
68	FRONT BUMPER PARKING SENSOR BRACKET	6	\$4.67	\$28.02	7
69	FRONT RADAR SENSOR	1		\$345.79	7
70	FRONT RADAR SENSOR BRACKET	1		R \$4.67	X
71	FRONT RADAR SENSOR SUPPORT BRACKET	1		R \$7.48	X
72	FRONT FENDER RH	1		Bu \$448.60	✓
73	FRONT FENDER INNER SHIELD RH	1		Sn \$116.82	X
74	FRONT DOOR RH	1		REPAIR	

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 29/03/2022
 Vehicle No: SNB9906B
 Model: TESLA MODEL 3 STANDARD RANGE
 Chassis: LRW3F7FJ5MC282819
 Reg.Year: 2021

Third Party Insurer: AIG
 Third Party Veh No: YL135K
 Date of Accident: 28/03/2022
 Estimator: KIT
 Surveyor:

SUB TOTAL	\$16,600.04
LESS 10%	\$1,660.00
PARTS TOTAL	\$14,940.04

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID INNER TRIM CLIPS	1		net \$50.00
2	REAR BUMPER CLIPS	1		net \$60.00
3	REAR END PANEL JOINT SEALANT	1		net \$80.00
4	REAR FENDER QUARTER GLASS SEALANT RH	1		net \$60.00
5	REAR FENDER INNER SHIELD CLIPS RH	1		net \$40.00
6	REAR WINDSCREEN GLASS SEALANT	1		net \$80.00
7	REAR NUMBER PLATE & HOLDER	1		\$50.00
8	FRONT BUMPER CLIPS	1		net \$60.00
9	FRONT FENDER INNER SHIELD CLIPS RH	1		net \$40.00
S/N TOTAL				\$520.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.

\$3,000.00 1700

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC.

\$2,800.00 1960

LABOUR CHARGES TO REMOVE & REPLACE FRONT & REAR PARKING SENSOR.

\$200.00 120

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM & UNHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER RH.

\$300.00 120

LABOUR CHARGES TO REMOVE & REPLACE REAR WINDSCREEN GLASS & ETC.

\$200.00 120

LABOUR CHARGES TO REMOVE & REFIX REAR QUARTER GLASS LH & ETC.

\$150.00 60

TO DAIGNOSIS FAULT CODE & RESET MEMORY.

\$200.00 7

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$120.00 40

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$250.00 60

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 29/03/2022
Vehicle No: SNB9906B
Model: TESLA MODEL 3 STANDARD RANGE
Chassis: LRW3F7FJ5MC282819
Reg.Year: 2021

Third Party Insurer: AIG
Third Party Veh No: YL135K
Date of Accident: 28/03/2022
Estimator: KIT
Surveyor:

	LABOUR TOTAL	\$7,220.00
KIT	TOTAL	\$22,680.04

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011