

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

MS FIRST CAPITAL INSURANCE LIMITED

6 Raffles Quay

#21-00

Singapore 048580

Tel: 62222311

Fax: 62223547

Attn: Motor Claim Department \ FIRST
CAPITAL

Your Ref No: TP 1124-8376

Claim Type: Third Party

Accident Date: 28 November 2024

TP Veh Reg No: SHD7237Y

Estimate No: **EST1512095**

Date: 29 Nov 2024

Policy No: P10708124R02

Veh Reg No: SMJ5532S

Make/Model: MITSUBISHI

OUTLANDER 2.0 CVT

Chassis No: GF7W0600635

Engine No: 4J11AC5069

Reg. Date: 12 Mar 2019

Estimate Repair Cost to Vehicle No: SMJ5532S

Description	Unit Price	Quantity	List Price SGD	Amount SGD
List Price				
1 REAR BUMPER WITH LOWER BLACK	1,400.00	1 PC	1,400.00	
2 REAR BUMPER SIDE RETAINER - LH/RH	25.00	2 PC	50.00	
3 REAR BUMPER CLIPS	10.00	10 PC	100.00	
4 REAR BUMPER LOWER, SILVER	490.00	1 PC	490.00	
5 REAR BUMPER LAMP - RH	130.00	1 PC	130.00	
6 REAR BUMPER REINFORCEMENT BRACKET - LH/RH	88.00	2 PC	176.00	
7 REAR BUMPER SIDE ARCH GARNISH - RH	130.00	1 PC	130.00	
8 TAILGATE	1,200.00	1 PC	1,200.00	
9 TAILGATE GLASS MOULDING	210.00	1 set	210.00	
10 TAILGATE REFLECTOR - RH-	490.00	1 PC	490.00	
11 TAILGATE OUTLANDER WORDINGS	110.00	1 PC	110.00	
12 TAILGATE MIVEC LOGO	105.00	1 PC	105.00	
13 TAILGATE WEATHERSTRIP-	250.00	1 PC	250.00	
14 TAILGATE LOCK	430.00	1 PC	430.00	
15 TAILGATE LOWER INNER TRIM	340.00	1 PC	340.00	
16 REAR END PANEL	350.00	1 PC	350.00	
17 REAR END PANEL TOP GARNISH	160.00	1 PC	160.00	
18 REAR END PANEL BUZZER	130.00	1 PC	130.00	
19 TAIL LAMP - RH	590.00	1 PC	590.00	
20 TAIL LAMP CLIPS - RH-	11.00	4 PC	44.00	
21 TAIL LAMP PANEL (UPPER) - RH-	350.00	1 PC	350.00	
22 TAIL LAMP PANEL (LOWER) - RH-	140.00	1 PC	140.00	
23 REAR FENDER COWLING (REAR) - RH	48.00	1 PC	48.00	
24 REAR FENDER COWLING CLIPS - RH	7.00	10 PC	70.00	
25 REAR EXHAUST SILENCER	650.00	1 PC	650.00	
26 REAR EXHAUST SILENCER TOP HEAT SHIELD	190.00	1 PC	190.00	
27 REAR EXHAUST SILENCER TOP MOUNTING	42.00	1 PC	42.00	
28 REAR CENTER EXHAUST	2,100.00	1 PC	2,100.00	
			10,475.00	
		Less 10%	-1,047.50	9,427.50
Special Net				
29 REAR BUMPER SENSOR	200.00	1 PC	200.00	
30 SEALANT	20.00	2 PC	40.00	
31 SPONGE TAPE	20.00	1 PC	20.00	
				260.00

Labour

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg


GST REG NO: 201006949C Company Reg No: 201006949C

32	TO KNOCK OUT DENTS ON REAR RH CHASSIS MEMBER, FLOOR PANEL, CUT/WELD END PANEL, TAILLAMP PANEL RH, REMOVE, REPLACE ACCIDENT PORTIONS	1,100.00	1 PC	1,100.00
33	TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,200.00	1 PC	1,200.00
34	TO CHECK WIRING	50.00	1 PC	50.00
35	TO REMOVE, REPLACE REAR BUMPER SENSOR	80.00	1 PC	80.00
36	TO REMOVE, REFIT GARNISH TO FACILITATE REPAIR	150.00	1 PC	150.00
37	TO ANTI RUST	80.00	1 PC	80.00
38	TO TRANSFER TAILGATE FITTINGS	100.00	1 PC	100.00
39	TO REMOVE, REFIT REAR GLASS	150.00	1 PC	150.00
40	TO REMOVE, REPLACE REAR EXHAUST SILENCER & CENTER EXHAUST	200.00	1 PC	200.00
				3,110.00

Total	12,797.50
Add GST @ 9%	1,151.78
Total Amount Payable SGD	13,949.28

SINGAPORE DOLLAR THIRTEEN THOUSAND NINE HUNDRED FORTY NINE AND CENTS TWENTY EIGHT ONLY

For Progressive Car Care Pte Ltd



AUTHORISED SIGNATURE