

Century Motors (Singapore) Pte Ltd (Co.Reg.No:192800002R)

6 Marsiling Lane,
Singapore 739145

Tel: 31572626 Email: claims@autoinsure.com.sg



INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	CM/11/24/0367
Policy No:	MPC24D00024802	Date of Loss:	02/12/2024 29/11/24
Vehicle Reg. No.:	SFG7698H	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHAN JIANGUANG, BENJAMIN		

Make/Model:	LEXUS NX200T, 2.0 EXECUTIVE (A)	Vehicle Reg. Date:	04/11/2016
Vehicle Colour:	WHITE		
Engine No:	8ARW374038	Chassis No:	JTJBARBZ702096104
Odometer:	88353 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) **8**

Present Location: CENTURY MOTORS (SINGAPORE) PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	12,540.00
Miscellaneous Items	310.00
Labour	3,300.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	16,150.00
+ GST 9.00% (\$\$)	1,453.50
Nett Amount (\$\$)	17,603.50

This claim is handled by: LEE SWEE HIAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97415749 / 62563561
Not Advise, Exp: to be advise
3/12/24 @ 4:15pm
p/p Resurvey before paint
No 2nd time part available
4-5 days.
Tanpin clkhants.com

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Dec 2024)
 Parts: M1-SUV LEXUS NX200T 2.0 EXECUTIVE (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Century Motors (Singapore) Pte Ltd/SFG7698H/02/12/2024 11:57
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER	0.00	0.00	de ✓ *520.00 F ✓
2	1		*FRT BUMPER BRKT RH	0.00	0.00	nn x *100.00 F
3	1		*FRT BUMPER BRKT LH	0.00	0.00	nn x? *100.00 F
4	1		*FRT GRILLE ASSY	0.00	0.00	en ✓ *600.00 F ✓
5	1		*FRT GRILLE CHROME	0.00	0.00	en ✓ *250.00 F
6	1		*FRT BUMPER LOWER MOULDING	0.00	0.00	de ✓ *350.00 F xnn
7	1		*FRT BUMPER AIR DUCT LH	0.00	0.00	nn x? *80.00 F
8	1		*FRT DAYLIGHT LH	0.00	0.00	nn x? *850.00 F
9	1		*FRT DAYLIGHT RH	0.00	0.00	nn x *850.00 F
10	1		*HEADLAMP RH	0.00	0.00	nn x? *800.00 F
11	1		*HEADLAMP LH	0.00	0.00	en ✓ 800.00 F ✓
12	1		*HEADLAMP BRKT RH	0.00	0.00	nn x *100.00 F
13	1		*HEADLAMP BRKT LH	0.00	0.00	nn x? *100.00 F
14	1		*FRT ENGINE UNDERCOVER	0.00	0.00	x *200.00 F
15	1		*FRT FENDER WHEELARCH LH	0.00	0.00	en ✓ *180.00 F ✓
16	1		*FRT FENDER LINER LH	0.00	0.00	nn x? *150.00 F
17	1		*FRT TOWING COVER	0.00	0.00	nn x? *50.00 F
18	1		*FRT SPOUNGE	0.00	0.00	en ✓ *60.00 F ✓
19	1		*FRT REINFORCEMENT	0.00	0.00	nn x? *350.00 F
20	1		*FRT SUPPORT PANEL	0.00	0.00	nn x? *750.00 F
21	1		*CONDENSER	0.00	0.00	nn x? *950.00 F bt
22	1		*RADIATOR	0.00	0.00	nn x *750.00 F
23	1		*BONNET	0.00	0.00	Ry *1,200.00 F
24	1		*BONNET HINGE RH	0.00	0.00	nn x *80.00 F
25	1		*BONNET HINGE LH	0.00	0.00	nn x *80.00 F
26	1		*FRT BUMPER LOWER LID	0.00	0.00	de ✓ *350.00 F ✓
27	1		*HEADLAMP WASHER PUMP LH	0.00	0.00	nn x *160.00 F
28	1		*HEADLAMP WASHER PUMP RH	0.00	0.00	nn x *160.00 F
29	1		*FRT PARKING SENSOR	0.00	0.00	nn x? *250.00 F
30	1		*FRT FENDER WHEELARCH RH	0.00	0.00	nn x *180.00 F
Sub Total (S\$)						11,400.00
+ Margin on L,N Items 10.00% (S\$)						1,140.00
Total Parts (S\$)						12,540.00

F=Franchise part.

Century Motors (Singapore) Pte Ltd/SFG7698H/02/12/2024 11:57. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	AIRCON GAS	100? 150.00 ✓
2	1	COOLANT	? 80.00 X
3	1	FRT BUMPER CLIPS	wa 40.00
4	1	FRT NUMBER PLATE AND HOLDER	bt 40.00
Sub Total (S\$)			310.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	New	500 1,400.00
2	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	New	500 1,200.00
3	TO VACUUM, WAXING & CLEAN INC SUNDRIES	New	X 150.00 nn
4	LABOUR TO REMOVE & REFIT FRT BOTH SIDE FENDER	New	X 200.00 nn
5	LABOUR TO RESET ADJUST FRT RADAR ECU AND PARKING ECU	New	200X? 350.00 nn
Gross Labour Cost (S\$)			3,300.00

Century Motors (Singapore) Pte Ltd/SFG7698H/02/12/2024 11:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >