

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / TP RES / CD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at W/O _____

of _____

Insured: _____

Policy No: _____

Claim No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Val: _____

(Policy Condition)

Remark: T/veh had commenced its repair at the time of inspection.

Bel. or Market Value: _____

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: EG5566E Yr Regn: 2018 / Nov

Type: (M) Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW X3 C.D. 2998

Colour Blue A/C: Insured / Std / NI / NA

Sp. Reading 72402 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBATS32040LE8.6946

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 295/35 R21

R: 295/35 R21

BS / DUN / EXNOVA / GY / FS / IZA / (MIC) / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 03/02/24

Survey held at JL Perfect

Des. of Damages (Frt) (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TPAIG</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes (✓)</u>
	<u>1st Survey : No ()</u>
	<u>MV : 112K</u>
	<u>PV : 76.6K</u>
	<u>Nett: 35.4K</u>
	<u>096E</u>

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Insp (\$ _____)

Survey Fee:

Transportation:

B + R.S. \$1

Photos

Others

Report Format: _____

Report Form / L.P. / C

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 02.12.2024

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **EG5566E**
MODEL : **BMW X3 M401**
DATE OF ACCIDENT : 30.11.20204
TIME OF ACCIDENT : 16:45 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Rehd</i>	1	\$ 2,485.50	\$ 2,485.50
2	FRONT BUMPER TOWING COVER <i>new</i>	1	\$ 78.45	\$ 78.45
3	FRONT BUMPER NUMBER PLATE GARNISH <i>Rehd</i>	1	\$ 120.87	\$ 120.87
4	FRONT BUMPER CORNER INNER SUPPORT <i>new</i>	2	\$ 123.85	\$ 247.70
5	FRONT BUMPER CAMERA <i>new</i>	1	\$ 2,138.20	\$ 2,138.20
6	FRONT BUMPER SIDE BRACKET <i>new</i>	2	\$ 67.55	\$ 135.10
7	FRONT BUMPER FOG LIGHT <i>Amhd</i>	2	\$ 771.80	\$ 1,543.60
8	FRONT BUMPER DAY FOG LIGHT COVER GARNISH <i>Amhd</i>	2	\$ 98.50	\$ 197.00
9	FRONT BUMPER FOG LIGHT CHROME <i>new</i>	2	\$ 115.85	\$ 231.70
10	FRONT BUMPER SENSOR <i>1 piece dmd</i>	2	\$ 769.55	\$ 1,539.10
11	FRONT BUMPER SENSOR HOLDER <i>new</i>	6	\$ 71.50	\$ 429.00
12	FRONT BUMPER CENTER GRILLE FRAME <i>cut</i>	1	\$ 375.80	\$ 375.80
13	FRONT BUMPER CENTER BOTTOM GARNISH <i>new</i>	1	\$ 315.40	\$ 315.40
14	FRONT BUMPER SIDE BOTTOM GARNISH <i>new</i>	2	\$ 61.40	\$ 122.80
15	FRONT BUMPER SIDE AIR DUCT RH <i>new</i>	1	\$ 65.85	\$ 65.85
16	FRONT BUMPER SPONGE <i>Amhd</i>	1	\$ 100.85	\$ 100.85
17	FRONT BUMPER CENTER BRACKET <i>new</i>	2	\$ 353.15	\$ 706.30
18	FRONT BUMPER REINFORCEMENT <i>Derhd</i>	1	\$ 1,325.50	\$ 1,325.50
19	FRONT BUMPER LOWER BEAM <i>new Best</i>	1	\$ 822.00	\$ 822.00
20	FRONT GRILLE C/W CHROME <i>Amhd</i>	2	\$ 554.00	\$ 1,108.00
21	FRONT LOWER AIR GUARD <i>Amhd</i>	1	\$ 319.40	\$ 319.40
22	FRONT LOWER GRILLE <i>Amhd</i>	1	\$ 302.45	\$ 302.45
23	HEADLAMP (LED) <i>Amhd</i>	2	\$ 6,809.70	\$ 13,619.40
24	HEADLAMP LOWER BRACKET <i>new</i>	2	\$ 274.70	\$ 549.40
25	HORN <i>new</i>	1	\$ 186.30	\$ 186.30

• **AIG** MOTOR CLAIMS DEPTS

VEHICLE NO

: EG5566E

MODEL

: BMW X3 M401

DATE OF ACCIDENT

: 30.11.20204

TIME OF ACCIDENT

: 16:45 HOURS

26	FRONT RADIATOR	1	\$ 981.60	\$ 981.60
27	FRONT RADIATOR MOUNTING	2	\$ 120.85	\$ 241.70
28	FRONT RADIATOR AIR GUARD	1	\$ 356.75	\$ 356.75
29	FRONT AIRCON CONDENSER	1	\$ 847.98	\$ 847.98
30	FRONT AIR DUCT	1	\$ 356.75	\$ 356.75
31	FRONT FENDER ARCED GARNISH RH (INNER)	1	\$ 238.60	\$ 238.60
32	FRONT FENDER ARCED GARNISH RH (OUTER)	1	\$ 345.70	\$ 345.70
33	FRONT FENDER COWLING RH	1	\$ 164.55	\$ 164.55
34	TAILGATE	1	\$ 2,465.65	\$ 2,465.65
35	TAILGATE LAMP	2	\$ 636.70	\$ 1,273.40
36	TAILGATE LOGO	1	\$ 120.15	\$ 120.15
37	TAILGATE EMBLEM 'X3'	1	\$ 90.50	\$ 90.50
38	TAILGATE EMBLEM 'M40i'	1	\$ 78.90	\$ 78.90
39	TAILGATE INNER TRIM	1	\$ 532.85	\$ 532.85
40	TAILGATE LOCK CONTROL MODULE SPONGE PROTECTOR	1	\$ 742.20	\$ 742.20
41	TAILGATE LOCK CONTROL MODULE	1	\$ 371.80	\$ 371.80
42	TAILGATE WINDSCREEN MOULDING C/W WINDSCREEN	1	\$ 1,149.85	\$ 1,149.85
43	TAILGATE DETECTOR	1	\$ 120.95	\$ 120.95
44	TAILGATE WEATHERSTRIP	1	\$ 185.85	\$ 185.85
45	REVERSE CAMERA	1	\$ 990.58	\$ 990.58
46	REAR FOOT SENSOR MODULE	1	\$ 550.85	\$ 550.85
47	REAR FOOT SENSOR (UPPER AND BOTTOM)	2	\$ 70.50	\$ 141.00
48	REAR FOOT SENSOR HOLDER	1	\$ 143.20	\$ 143.20
49	REAR BUMPER	1	\$ 1,838.56	\$ 1,838.56
50	REAR BUMPER CENTER	1	\$ 380.65	\$ 380.65
51	REAR BUMPER BOTTOM GARNISH	1	\$ 137.60	\$ 137.60
52	REAR BUMPER REFLECTOR	2	\$ 60.90	\$ 121.80
53	REAR BUMPER TOW HOOK COVER	1	\$ 91.85	\$ 91.85
54	REAR BUMPER SENSOR	4	\$ 269.55	\$ 1,078.20
55	REAR BUMPER SENSOR HOLDER	6	\$ 145.20	\$ 871.20
56	REAR BUMPER REVERSE SENSOR WIRE HARNESS	1	\$ 850.15	\$ 850.15
57	REAR BUMPER BOTTOM SIDE GARNISH RH	1	\$ 146.30	\$ 146.30
58	REAR BUMPER REINFORCEMENT	1	\$ 832.45	\$ 832.45
59	REAR BUMPER SIDE BRACKET (PLASTIC)	2	\$ 199.60	\$ 399.20
60	REAR BUMPER CENTER BRACKET (PLASTIC)	2	\$ 199.50	\$ 399.00
61	TAIL LAMP	2	\$ 582.45	\$ 1,164.90
62	TAILLAMP PANEL RH	1	\$ 640.80	\$ 640.80
63	TAIL LAMP SIDE GARNISH	2	\$ 80.90	\$ 161.80

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **EG5566E**
 MODEL : **BMW X3 M401**
 DATE OF ACCIDENT : 30.11.20204
 TIME OF ACCIDENT : 16:45 HOURS

12	REAR BUMPER CLIP (SET) <i>den</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
13	REAR BUMPER BOTTOM GARNISH CLIP (SET) <i>den</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
14	TAILGATE SEALANT <i>den</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
15	TAILGATE INNER TRIM CLIP (SET) <i>den</i>	1	\$ 50.00	\$ 50.00	<i>30</i>
16	TAILGATE WINDSCREEN GLASS SEALANT <i>den</i>	1	\$ 100.00	\$ 100.00	<i>50</i>
17	TAILGATE WINDSCREEN GLASS INNER SEAL <i>den</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
18	TAILGATE WINDSCREEN GLASS SOLAR FILM <i>den</i>	1	\$ 550.00	\$ 550.00	<i>+</i>
19	TAIL LAMP CLIP (SET) <i>den</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
20	TAIL LAMP SIDE GARNISH CLIP (SET) <i>den</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
21	REAR FENDER COWLING CLIPS (SET) <i>den</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
22	REAR FENDER INNER TRIM CLIPS (SET) <i>den</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
23	REAR FENDER QUARTER GLASS SEALANT <i>den</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
24	REAR FENDER QUARTER GLASS INNER SEAL <i>den</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
25	REAR FENDER QUARTER GLASS SOLAR FILM LH <i>den</i>	1	\$ 350.00	\$ 350.00	<i>+</i>
26	REAR WHEEL ARCED GARNISH CLIP (SET) <i>den</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
27	REAR END PANEL TOP GARNISH CLIPS (SET) <i>den</i>	1	\$ 30.00	\$ 30.00	<i>20</i>
28	REAR END PANEL INSULATION SEAL <i>den</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
29	BRAKE OIL <i>den</i>	1	\$ 50.00	\$ 50.00	<i>+</i>

TOTAL \$ 2,760.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	<i>400</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	<i>250</i>
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	<i>+</i>
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	<i>+</i>
5	REFOCUS HEADLAMP BEAM	\$ 80.00	<i>+</i>
6	REMOVE AND REFIX FRONT BUMPER SENSOR	\$ 80.00	<i>50</i>
7	REMOVE AND REFIX FRONT BUMPER CAMERA	\$ 80.00	<i>50</i>

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **EG5566E**
 MODEL : **BMW X3 M401**
 DATE OF ACCIDENT : 30.11.20204
 TIME OF ACCIDENT : 16:45 HOURS

64	REAR BLIND SPORT SENSOR RH <i>new</i>	1	\$ 1,365.45	\$ 1,365.45	+
65	REAR FENDER RH <i>new</i>	1	\$ 2,640.95	\$ 2,640.95	+
66	REAR FENDER INNER COWLING <i>new</i>	2	\$ 185.98	\$ 371.96	+
67	REAR FENDER INNER TRIM <i>new</i>	2	\$ 439.80	\$ 879.60	+
68	REAR WHEEL ARCED GARNISH <i>new</i>	2	\$ 245.20	\$ 490.40	+
69	REAR END PANEL (INNER) <i>Rept</i>	1	\$ 556.98	\$ 556.98	+
70	REAR END PANEL (OUTER) <i>Dented</i>	1	\$ 651.55	\$ 651.55	-
71	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 245.52	\$ 245.52	-
72	REAR FLOOR TOP BOARD <i>new</i>	1	\$ 830.70	\$ 830.70	+
73	REAR SIDE TRAY RH <i>new</i>	1	\$ 121.50	\$ 121.50	+
74	REAR ACTIVATED CHARCOAL FITTER <i>could</i>	1	\$ 289.85	\$ 289.85	-
75	REAR ACTIVATED CHARCOAL FITTER HOSE <i>new</i>	1	\$ 123.55	\$ 123.55	+
76	CENTER EXHAUST PIPE INSULATOR <i>new</i>	1	\$ 200.15	\$ 200.15	+
77	CENTER EXHAUST MOUNTING <i>new</i>	4	\$ 28.15	\$ 112.60	+
78	CENTER EXHAUST PIPE BRACKET <i>new</i>	2	\$ 78.78	\$ 157.56	+
79	REAR EXHAUST PIPE WITH MUFFLER <i>Best</i>	1	\$ 4,892.70	\$ 4,892.70	+
80	REAR EXHAUST MOUNTING <i>Best</i>	4	\$ 29.70	\$ 118.80	29.70
81	REAR EXHAUST PIPE BRACKET <i>Best</i>	1	\$ 78.70	\$ 78.70	✓
82	REAR EXHAUST MUFFLER INSULATOR (SIDE) <i>amplified</i>	1	\$ 116.85	\$ 116.85	-
83	REAR EXHAUST MUFFLER INSULATOR (CENTER) <i>amplified</i>	1	\$ 200.45	\$ 200.45	-
84	REAR CROSSMEMBER <i>best ?</i>	1	\$ 2,895.65	\$ 2,895.65	+
85	REAR LOWER ARM LH <i>best ?</i>	1	\$ 685.30	\$ 685.30	+

TOTAL PRICE \$ 68,698.26
 LESS 5% \$ 3,434.91
SUB TOTAL PRICE \$ 65,263.35

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>could</i>	1	\$ 80.00	\$ 80.00	-
2	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
3	FRONT BUMPER FOG LAMP LOWER GARNISH CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
4	FRONT BUMPER CENTER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
5	FRONT BUMPER CENTER BOTTOM GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	30
6	FRONT BUMPER NUMBER PLATE GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	20
7	FRONT LOWER GRILLE CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
8	FRONT AIR DUCT BASE GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
9	FRONT FENDER ARCED GARNISH CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
10	FRONT FENDER COWLING CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
11	REAR NUMBER PLATE <i>Best</i>	1	\$ 80.00	\$ 80.00	✓

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **EG5566E**
 MODEL : **BMW X3 M401**
 DATE OF ACCIDENT : 30.11.20204
 TIME OF ACCIDENT : 16:45 HOURS

7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 680.00	200
---	--	----------------------	-----

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	1000
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	750
3	TUFF COAT	\$ 250.00	60
4	WIRING CHECK	\$ 80.00	30
5	CONDUCT WATER LEAKAGE TEST	\$ 180.00	x
6	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 180.00	60
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
8	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
9	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	\$ 80.00	50
10	REMOVE AND REFIX BLIND SPORT SENSOR AND REPROGRAMMING	\$ 1,200.00	x
11	FOUR WHEEL ALIGNMENT	\$ 120.00	80
12	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x
13	REMOVE AND REFIX REAR SMART SENSOR AND RESET	\$ 550.00	180
14	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
15	RESET TAILGATE AUTO SYSTEM	\$ 350.00	x

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **EG5566E**
MODEL : **BMW X3 M401**
DATE OF ACCIDENT : 30.11.20204
TIME OF ACCIDENT : 16:45 HOURS

16	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	100
17	REAR CHASSIS ALIGNMENT	\$ 250.00	+

TOTAL \$ 11,300.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 68,023.35
TOTAL LABOUR COST : \$ 11,300.00
TOTAL REPAIR COST : \$ 79,323.35

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: