(08/11/13) wef REF:								
ASS PEC. BY: Marcus (5/11)	24/20023/4vh3							
ASSIGNMENT								
From: Date:	Veh No: GBL 6-889M Yr Regn: 28/12/21							
Estimated Cost:	Type: M.Car / M.Cycle / Bus (Van / Lorry / Taxi / Prime Mover /							
OD TO WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or							
To Inspect Vehicle No: 6526499M	Make: To yoto hiace 2.0 Dxc.c 1998							
at Workshop m/s hymo to 2 2m	Colour S, Ne A/C: Insured / Std / NI / NA							
of (	Sp.Reading 1250/9 T/Radio: Insured / Std / NI / NA							
Insured: YN S (32A)	Eng/No:							
Policy No. D22MCV0010320  Claims No. MCV2024D0014339	C/No: TRH 2000 347863							
Oldinio 140.	Gen. Cond: Good / Fair / Poor / Burnt							
Sum Insured: Excess: \$ 600	Steering: Inorder / Jammed / Leaked / Burnt or							
(Client's Record)  Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or							
wake of ven.	Modi: Nil S/Rim / STD A/Rim or							
(Policy Condition)	Tyre Size: F: /95-705							
Remark: The veh had commenced its  N/S  O/S	R: BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /							
repair at the time of inspection.	TOYO/YOKO or gren/grow							
Bal. or Market Value: 877k.	Front Rear							
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm							
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 6 mm L/Bal. 6 mm							
Est. Repairs: days Res.: Yes or No	D.O.A. 01/11/24 D.O.I. 04/11/24							
Lum Sum: % 3 Val.: Yes or No	Survey held at							
CA / REV / REP. / 24 HRS C 340M	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or							
Vehicle: IN / OUT  Date: Person Contacted: 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	0/5 dry 0/5 Body-							
Date / Time Action / Instruction Dep 11 k	The U/C / Chassis frame / Body Structure affected due to collision.							
	1517.30							
6/1/24 P/P # 14535-56 informed	Dev. ( (red 5131.97, 26%)							
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 7							
Commenced Commen	Resurvey No. of Trip: Survey Fee:							
Date/Time, File Return to?	Transportation:							
Add Fee:	: Site Insp (\$ )s+Rs,sl							
Danast Farmat	: Interview (\$ ) Photos							
Report Format:	: Tech. Invs (\$ ) Others							
Lump Sum / I.B.I: (\$	: Weekend (\$							

TOTAL

### > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

/ehicle Owner Particulars	
Owner ID Type:	Company
Owner ID: /ehicle Details	340M
/ehicle No.:	GBL6599M
/ehicle to be Exported:	No
ntended Deregistration Date:	04 Dec 2024
/ehicle Make:	ТОУОТА
/ehicle Model:	HIACE 2.0 DX AUTO
Primary Colour:	Silver
Manufacturing Year:	2021
Engine No.:	1TR2384062
Chassis No.:	TRH2000347863
Maximum Power Output:	
Open Market Value:	\$27,071.00
Original Registration Date:	28 Dec 2021
First Registration Date:	28 Dec 2021
ransfer Count:	0
Actual ARF Paid: ntended PARF Rebate Details	\$1,354.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	
ARF Rebate Amount: ntended COE Rebate Details	\$0.00
COE Expiry Date:	27 Dec 2031
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$32,500.00
COE Rebate Amount:	\$22,950.00
otal Rebate Amount:	\$22,950.00

The information contained herein is correct as at 04 Dec 2024

## > Back to OneMotoring

# **Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	340M
Vehicle Details	
Vehicle No.:	GBL6599M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	08 Nov 2022
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE 2.0 DX AUTO
Primary Colour:	Silver
Manufacturing Year:	2021
Engine No.:	1TR2384062
Chassis No.:	TRH2000347863
Maximum Power Output:	
Open Market Value:	\$27,071.00
Original Registration Date:	28 Dec 2021
First Registration Date:	28 Dec 2021
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$1,354.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	¥
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2031
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$32,500.00
COE Rebate Amount:	\$26,000.00
Total Rebate Amount:	\$26,000.00
The state of the second content of the secon	The second secon

The information contained herein is correct as at 08 Nov 2022



### ACCIDENT REPORTING CENTRE & AUTHORISED WORKSHOP

## **HUP MOTOR TRADING & SERVICE**

BLK 9004 TAMPINES STREET 93 #01-120 SINGAPORE 528838 TEL: 67840039 (24 hrs) HP: 98154655 Email: hupmotor@gmail.com

#### INDIA INTERNATIONAL INSURANCE PTE LTD

Go Reg, No. 198703792k | GST Reg, No. M2-0078806-X 6 Raffles Quay #22-00 Singapore 048580 Office (65) 63476100 Website www.iii.com.sg

**COVER:** Comprehensive

### CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

All Accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

**GBL6599M** TRH2000347863

28 Dec 2023 27 Dec 2024

### CERTIFICATE NO.: D22MCV0010320 01

1. Index Mark and Registration Number of Vehicle

Chassis No

2. Name of Policyholder

Effective date of Insurance

Expiry date of Insurance

Persons or Classes of Persons entitled to drive\*

Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

DL REPAIR & AIRCON SERVICES PTE. LTD.

- a) Use in connection with the Policyholder's business.
- b) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.
- c) Use for social, domestic and pleasure purposes.

#### The Policy does not cover

- a) Use for hire or reward.
- b) Use for racing, pace-making, reliability trial or speed-testing.
- c) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

\*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Excess Section I

: SGD600.00

Windscreen Excess: SGD100.00

Hire Purchase Company : United Overseas Bank Limited

FOR DRIVERS BELOW 21 YEARS OR ABOVE 69 YEARS OF AGE &/OR LESS THAN 2 YEARS SINGAPORE DRIVING LICENCE, DDITIONAL EXCESS OF \$2500/- ON SECTION I WILL BE APPLICABLE.

I/We HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Agent/Broker

: A000038/M Plus Consultancy


Date of Issue

: 20/12/2023 15:16:25

M.Z. 300C - GOODS CARRYING(ORGANIZATION)

For India International Insurance Pte Ltd

Nalini Venugopal MD & CEO



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. \$8228199A





LAU CHEE KIAT, JEFFREY (LIU ZHIJIE, JEFFREY)

刘

CHINESE Date of birth 14-09-1982 M Country of birth SINGAPORE

INSURED OF : GBL 6599 M

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Motor Cars=< 3000kg with =<7 passengers, exclusive 10 Jul 2006 of the driver; and other motor vehicles =< 2500kg

NP 428A

3826617



IC No. S8228199A

18-03-2006


APT BLK 111 WOODLANDS STREET 13 #07-76 SINGAPORE 730111

PREMIUM AD


# sgcarmart

(2) Login | Sign Up Used Electric Loan Rent Sell Directory e-Shop Insurance Articles Forum

New Resources



Mileage Car Make Price Depre 2021 Eng. Cap Owner 10 Vehicles




Sort by Any Status, Date Posted (Newest)

Car Model

1 owner unit! Well taken care of by previous owner! Low mileage unit! Value for money! Powerful engine with auto gearbox! Auto LED headlight unit! Enjoy lifetime servicing secomon and unlimited mileage warranty! We take in high trade in for your current unit! High loan available with immediate approval! Call now to secure and view this unit now! ABS Bus Pte Ltd|Posted 02-Dec-2024 Compare



previous owner! Well taken care! Rear aircon unit. No repair needed. High trade in SG Motor Link Pte Ltd|Posted 02-Dec-2024 Compare



1 owner closed panel van with super low mileage! Very well maintained & original condition! It's practically brand new! Vehicle comes with full wrapping interior with mesh & plywood carpet! Free lifetime servicing every 10,000km and 2

# 哈汽車貿易服務

# **HUP MOTOR TRADING & SERVICE**

The phe sepe say

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W 3163/12/24 Date: 2nd December 2024 More 2024

Not Arthur Marins

Eynes \$600

41.1724

P/2 \$ 14535.56

7 days. Your Ref: The Claim's Manager Motor Claims Dept. INDIA INTERNATIONAL INSURANCE PTE. LTD. 6, Raffles Quay, #22-00, Singapore 048580 Name Of Insured: M/S DL Repair & Aircon Services Pte. Ltd. Date Of Accident: 01/12/24 (23:45hrs) Policy Number: D22MCV0010320 01 Estimate cost of repair to TOYOTA HIACE (A) 2.0 Van - GBL 6599 M 1 pc front grille Comp MQ\$ 546.70 -1 pc front grille inner support base 488.20 × 11 6 pcs front grille clips & stopper 14.60 M 87.60 1 pc front bumper 7.5 942.00 cne 238.06 -1 pc front bumper o/s side bracket 10 pcs front bumper clips 6.00 res 60.00 CM 1,390.10 1 pc o/s head lamp comp. 1 pc o/s head lamp lower bracket clip 31.'17 X 3 W 446.14 -1 pc front o/s corner panel 1 pc front o/s step panel garnish 244.92 ⊀ \$3196.70 3,465.47 V 3,212.98 V 1 pc front o/s door 3,212.98 1 pc front o/s door side mirror comp & 2907-30 2 pcs front o/s door top & low hinge Suffer \$ \$ 165.79 331.58 E 1278.502 1 pc front o/s door checker 1 pc front o/s door weatherstrip grand 260.60 1 pc front o/s door lock outer handle 1 pc front o/s door lock knob 35.10 J more 1 pc front o/s door glass regulator 11 386.40X 16 pcs front o/s door trim board clips 4.90 11 78.40 X 1 pc front o/s door lock pillar panel one 761.20 Daye Jn 802.20 C 1 pc front o/s door inner lock en 3,949.10 -Dye/2 355.30 2 1 pc o/s side door \$ 3221.20 1 pc o/s side door lock 1 pc o/s side door glass inner seal My 98.80 -1 pc o/s side door glass inner damper M 75.00 NO 60.00405/N 1 pc o/s side door glass sealant 16 pcs o/s side door inner trim board clips 4.90/1 78.40 X \$ 19,052.07 Less 25% \$ 4,763.02 \$ 14,289.05 AM 80.00 S.N 1 pc front o/s door company sticker To wiring check up for affected wiring system, including radio, reverse camera & adjust headlight alignment. 100.00 20 \$ 14,469.05 Balance C/F..... 27910.26A60

Supplementary Bell-B/4

# 哈汽車貿易服務

# **HUP MOTOR TRADING & SERVICE**

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3163/12/24 Your Ref: Date: 4th DEC 2024

The Claim's Manager
Motor Claims Dept.
INDIA INTERNATIONAL INSURANCE PTE. LTD.
6, Raffles Quay, #22-00,
Singapore 048580

Name Of Insured: M/S DL Repair & Aircon Services Pte. Ltd. Date Of Accident: 01/12/24 (23:45hrs)

Policy Number: D22MCV0010320\_01

## Supplementary Bill for TOYOTA HIACE (A) 2.0 Van - GBL 6599 M

1 pc front o/s corner panel
2 pcs front o/s corner panel holder bracket \$ 61.00 17 \$ 122.00 \times

257

# 哈汽車貿易服務

# **HUP MOTOR TRADING & SERVICE**

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Re	ef:	3163/12/24	Your Ref:		Date: _	2nd De	cember	2024
	M/	S INDIA INTERN	ATIONAL INSURANCE	PTE. LTD.,	Balance	B/F	. \$ 14	,469.05
	ch	annel, weather:	t o/s door trim bo strip, lock, regul ry parts into new	ator, motor,	oulding, hinge, c	necker,		200.00.60
			k o/s side door tr k necessary parts.		r, inner	lock,	170	150.00 60
	To	remove & refin	k o/s side door gl	ass & necessa	ry parts	,		150.00[00
	do	or run channel	k front o/s cushio , safety belt, roo to enable repair	f lining, upn	olstery a	kc	0.61	180.00 100
	To	check & adjust	t front wheel alig	nment & balan	cing.		11	120.00
	st: do	raighten & knoc or pillar pane ove parts.	remove & cut out cking out front o/ l & necessary part ay painting on all	s wheel panel s, to weld, r	, front enew & a.	o/s lign		1000 ,000.00 1100 ,000.00
							PRODUCTION AND MARKS	,089.05
	Dol	llars : Ninetee	n Thousand Eighty	Nine And Cent	ts Five (	nly.	P-1	6034.08 252
		-					0	12025-56
		HUP MOTOR TRAD	PARTICISATION OF THE PARTICISA	LKK Auto Consultar the Repairer of the • To resurvey before/aft • To display damaged p • Parts prices are subjection. • Third party survey is o	following: erepray politing art., in a recu of to confirmation		1-	2440

Acknowledged by Repairer