

KING'S WAY AUTOMOTIVE PTE LTD

Company Registration No. 202440629G
435B Northshore Drive #07-1523 Singapore 822435
Email : kingswayclaim@gmail.com

Tel : 81890682

ESTIMATE

EFFICIENT TOWING SERVICES
402B FERNVALE LANE
#22-229
SINGAPORE 792402

Accident Date: 13/11/2024
Vehicle No.: YP3294T
Model: ISUZU NPR75UH5A AMT
Chassis/Eng#: JAANPR75HF7106333/4HK1426809

SUPPLEMENTARY ITEMS

No	Description Of Parts		Qty	Unit Price	Amount
1	REAR TOW CARRIER <i>Best</i>	S	1	\$ 4,800.00	\$ 4,800.00
2	REAR TOW CARRIER HYDRAULIC HOSE (DISCHARGE) <i>gap</i>	S	1	\$ 450.00	\$ 450.00
3	REAR TOW CARRIER HYDRAULIC HOSE (RETURN) <i>gap</i>	S	1	\$ 450.00	\$ 450.00
4	REAR TOW CARRIER HYDRAULIC PUMP <i>Ryis</i>	S	1	\$ 4,800.00	\$ 4,800.00
5	REAR TOW CARRIER LOCK PIN <i>also in</i>	S	1	\$ 400.00	\$ 400.00
Sub-total :					\$ 10,900.00
Parts Total:					\$ 10,900.00

LABOUR

1	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	\$ 1,500.00
2	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	\$ 2,000.00
Labour total		\$ 3,500.00
Parts & Labour total		\$ 14,400.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adnan G
h/s 04 days