

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24060031/EVCE2**Date:** 11/07/2024**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MAA00607
Claimant Vehicle No :	SHD6828Z	Insured Vehicle No :	SMM7175K
Date of Loss:	10/06/2024	Nature of Claim:	TP
		Claim No:	M2403264

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD6828Z		
Make & Model:	TOYOTA PRIUS TAXI, 1.8 HATCHBACK(AT) (2WD) (A)	Engine No:	2ZR2G82339
Reg. Date:	30/09/2020 (Man. Year: 2020)	Chassis No:	JTDKB3FU603091577
Colour:	Blue	Odometer:	574089 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,149.00	1,149.00	0.00	0.00
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	300.00	180.00	120.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,461.00	1,341.00	120.00	8.21
Approved Total (Overridden) (S\$)		1,050.00		
(S\$)	1,461.00	1,050.00	411.00	28.13
+ GST 9.00/9.00% (S\$)	131.49	94.50	36.99	28.13
Nett Amount (S\$)	1,592.49	1,144.50	447.99	28.13

INSPECTION

Date of Assignment:	11/06/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	11/06/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	1.0 days		

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jul 2024)
Parts:	144	TOYOTA PRIUS TAXI 1.8 HATCHBACK(AT)(2WD) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD6828Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WING MIRROR ASSY RH	Broken	1,390.10 FL	*1,390.10 FL
2	1		*FRONT WING MIRROR COVER RH	Broken	141.90 FL	*141.90 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					1,532.00	1,532.00
- List Item Discount on L Items 25.00/25.00% (\$\$)					383.00	383.00
Total Parts (\$\$)					1,149.00	1,149.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	150.00	100.00
2	SPRAY PAINTING	New	150.00	80.00
Gross Labour Cost (\$\$)			300.00	180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >