

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0504/2024/EQ
DATE : 28-Jun-24
WIP : 21083

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/6/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

3 Days - OK - Allan Boo

7-Aug-24

OWNER'S NAME : AWFULLYCHOCOLATE PTE LTD
ADDRESS : 70 GRANGE ROAD
#08-01
SINGAPORE 249574
TELEPHONE : HP +65 96929330
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210065355-03
VEHICLE NO : **SKJ 2200 T**
MODEL CODE : AUDI Q7 2.0 TFSI QU
MODEL YEAR : 28/6/2021
ENGINE NO : CYR 103508
CHASSIS NO : WAUZZZ4M0MD010750
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Jun-24
PLACE OF ACCIDENT : FUNAN MALL CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SKJ 2200 T.**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS	
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	\$	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,000.00	\$	600.00
3	TO RESRPAY REAR BUMPER, REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS.	\$	2,000.00	\$	1,600.00
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	480.00	\$	292.00
TOTAL LABOUR CHARGES		:	\$ 3,840.00	\$	2,852.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKJ 2200 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER - UPPER	1	\$ 1,641.00	
2	REAR BUMPER - LOWER	1	\$ 2,307.00	
3	REAR BUMPER FIXING PARTS	1	\$ 490.00	
4	REAR BUMPER SPOILER	1	\$ 1,580.00	
5	REAR REINFORCEMENT BEAM	1	\$ 1,729.00	
6	REAR REINFORCEMENT BEAM SEAL	2	\$ 36.00	
7	REAR BUMPER HOLDING STRAP	1	\$ 231.00	
8	REAR BUMPER GUIDE SECTION - CENTER	1	\$ 178.00	
9	REAR BUMPER GUIDE SECTION - RH	1	\$ 80.00	
10	REAR BUMPER TAILLIGHT - RH	1	\$ 452.00	\$ 361.60
11	REAR PARKING AID SENSOR	1	\$ 286.00	
12	REAR PARKING AID SENSOR SEAL RING	4	\$ 11.00	
13	REAR WHEEL ARCH COVER - LH / RH	2	\$ 866.00	\$ 692.00
14	SUNDRIES		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 10,387.00	\$ 1,053.60
TOTAL LABOUR CHARGES		:	\$ 3,840.00	\$ 2,852.00
GRAND TOTAL		:	\$ 14,227.00	\$ 3,905.60

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT