

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURAN	CE LTD	Ref:	CS/INC24120029/Eqh3e2	
	75 BRAS BASAH ROAD		Date:	17/12/2024	
	INCOME CENTRES	NCOME CENTRE SINGAPORE 189557		INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGW 8183Z	Veh. Inspected	SNL 8426Z	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1305435-002	Excess	\$0.00	
	Assign From	LIM SERENE	Assign Date	03/12/2024	
2.	2. Vehicle Details				
	Make & Model	HONDA SHUTTLE	C.C	1496	
	Engine No.	LEB7606661	Year of Reg.	07/08/2023	
	Chassis No.	GP72205461	Colour	GREEN	
	Odometer	116247 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	185/60 R15	FIRENZA	5	
	L/H Front Tyre	185/60 R15	FIRENZA	5	
	R/H Rear Tyre	185/60 R15	FIRENZA	5	
	L/H Rear Tyre	185/60 R15	FIRENZA	5	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5. General Information					
	Accident Date	22/11/2024	Inspection Date	03/12/2024 (11:50)	
	Survey held at	MIRAI AUTO PERFORMANCE PTE LTD - 8 KAKI BUKIT AVENUE 4 #08-19 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days