



Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TP INC
Xiao Chun

HENG SWEE BOON
79 ANCHORVALE CRESCENT #03-17
SINGAPORE 544624

TAX INVOICE

Repair Code : CLM18475

Date in : 02/12/2024

Vehicle Num. : SNN5335L

Model : HONDA VEZEL 1.5G CVT

Chassis/Eng# : RV31013977/L15Z1016529

Contact : 97962816

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Repr</i>	1	871.20	+ 871.20
FRONT BUMPER LOWER LID <i>lt</i>	1	440.90	✓ 440.90
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	22.50	+ 45.00
FRONT RH DOOR SIDE MIRROR <i>lt</i>	1	1554.70	<i>1180</i> 1554.70
FRONT RH DOOR SIDE MIRROR COVER <i>new</i>	1	89.70	+ 89.70
FRONT RH FENDER <i>Repr</i>	1	785.20	+ 785.20
FRONT RH FENDER ARCH GARNISH <i>lt</i>	1	198.20	✓ 198.20
FRONT RH FENDER INNER SHIELD <i>new</i>	1	138.20	+ 138.20
FRONT RH HEADLAMP <i>lt</i>	1	2150.70	<i>1850</i> 2150.70
FRONT RH KNUCKLE ARM <i>new</i>	1	335.80	+ 335.80
FRONT RH KNUCKLE ARM BEARING <i>new Repr</i>	1	168.90	<i>42</i> 168.90
FRONT RH LOWER ARM <i>new</i>	1	398.70	+ 398.70
FRONT RH SHOCK ABSORBER <i>new</i>	1	316.90	+ 316.90
FRONT RH SPORT RIM <i>lt</i>	1	926.40	<i>550/50</i> 926.40
FRONT RH STABILIZER LINK <i>new</i>	1	98.70	+ 98.70

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HENG SWEE BOON
79 ANCHORVALE CRESCENT #03-17
SINGAPORE 544624

Contact : 97962816

TAX INVOICE

Repair Code : CLM18475

Date in : 02/12/2024

Vehicle Num. : SNN5335L

Model : HONDA VEZEL 1.5G CVT

Chassis/Eng# : RV31013977/L15Z1016529

	Subtotal before discount		8,519.20
Percentage discount 20%		4138.70	1,703.84
	Sub-total 1	3310.96	6,815.36
FRONT BUMPER CLIPS - SET	1	80.00	80.00
FRONT RH FENDER ARCH GARNISH CLIPS - SET	1	40.00	40.00
FRONT RH FENDER INNER SHIELD CLIPS - SET	1	40.00	40.00
FRONT RH TYRE 215/60R16	1	500.00	500.00
	Subtotal before discount		660.00
Percentage discount 0%			0.00
	Sub-total 2		660.00
	Parts-total		7,475.36

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

To road test driving, check and resetting wheel alignments system.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

30	80.00
80	300.00
80	100.00
300	1,000.00
200	900.00
30	120.00

Labour Total

2,500.00

Parts & Labour Total

9,975.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval

Acknowledged by Repairer

Signature:

Date:

*** This is a computer-generated document which requires no signature ***

3.81K

total: 4810.96
H/S: 3.81K