

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TP INC
Xiao Chan

JUI YU TING
BLK 641 YISHUN ST 61 #12-20
SINGAPORE 760641

TAX INVOICE

Repair Code : CLM18476

Date in : 29/11/2024

Vehicle Num. : JVV8785

Model : MAZDA CX-8 2.5G 2WD HIGH PLUS

Chassis/Eng# : PPIKGA331PM300380/PY10857927

Contact : 85250477

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Delnd</i>	1	1524.00	1,524.00 1125
REAR BUMPER LOWER LID <i>Delnd</i>	1	773.00	773.00 415
REAR BUMPER REFLECTOR L/R <i>new</i>	2	98.00	+ 196.00
REAR BUMPER REINFORCEMENT <i>Dented</i>	1	553.00	553.00
REAR BUMPER REVERSE SENSOR COVER L/R <i>2 pieces new</i>	4	32.00	128.00 64
REAR BUMPER REVERSE SENSOR L/R <i>2 pieces new</i>	4	235.00	940.00 470
REAR BUMPER REVERSE SENSOR WIRE HARNESS <i>new</i>	1	140.00	+ 140.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	35.00	+ 70.00
REAR BUMPER TOW HOOK COVER L/R <i>RT Delnd</i>	2	48.00	96.00 48
REAR BUMPER UNDER COVER <i>new</i>	1	78.00	+ 78.00
REAR END PANEL <i>new Repair Dented</i>	1	676.00	676.00
REAR END PANEL ANTENNA SENSOR <i>Delnd</i>	1	89.00	89.00
REAR END PANEL INNER TOP GARNISH <i>new</i>	1	169.00	+ 169.00
REAR TAILGATE <i>Dented</i>	1	1877.00	1,877.00
REAR TAILGATE 'CX-8' EMBLEM <i>new</i>	1	66.00	66.00
REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	72.00	+ 72.00
REAR TAILGATE 'SKYACTIV' EMBLEM <i>new</i>	1	61.00	61.00
REAR TAILGATE HINGES L/R <i>new</i>	2	46.00	92.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

JUI YU TING
BLK 641 YISHUN ST 61 #12-20
SINGAPORE 760641

Contact : 85250477

TAX INVOICE

Repair Code : CLM18476

Date in : 29/11/2024

Vehicle Num. : JVV8785

Model : MAZDA CX-8 2.5G 2WD HIGH PLUS

Chassis/Eng# : PP1KGA331PM300380/PY10857927

REAR TAILGATE INNER GUIDE STOPPER L/R	2	10.60	+	21.20
REAR TAILGATE INNER TRIM BOARD	1	548.00	+	548.00
REAR TAILGATE LOCK STRIKER	1	55.00	+	55.00
REAR TAILGATE MECHANISM LOCK	1	933.00	+	933.00
REAR TAILGATE WEATHER STRIP	1	154.00	+	154.00
Subtotal before discount				9,311.20
Percentage discount 20%				1,862.24
Sub-total 1				7,448.96
Parts-total				9,311.20

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

To repair exhaust pipe

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	80.00
To remove, reinstall tailgate windscreen	120 150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	1710 80.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	800 1,000.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	Adm LG 800 1,000.00
To apply anti-rust chemical on repaired and replaced panel.	2/S 03/12/24 80.00
To remove, reinstall tailgate mechanism and check for function	60 80.00
To repair exhaust pipe	400 250
Labour Total	2,470.00
Parts & Labour Total	11,781.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are ***This is a computer-generated document which requires no signature.***
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 6383.60

L/S: SIK ✓