

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	INCOME INSURAN	ICE LTD		Ref:	CS/INC24120031/Aqh3m4(N)
	75 BRAS BASAH R INCOME CENTRES	ROAD SINGAPORE 189557		Date:	03/03/2025
	ATTN: CHRYLLIS	HAUQ		Code:	INC
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SNQ 1914B	Veh. Inspected	k	JVV 8785
	Policy No.		Coverage (\$)		0.00
	Claim No.	MT/1306811-001	Excess (\$)		0.00
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		03/12/2024
2. Vehicle Particulars & Condition					
	Make & Model	MAZDA CX-8	c.c		2488
	Engine No.	HIDDEN	Year of Reg.		2022
	Chassis No.	PP1KGA331PM300380	Colour		BLACK
	Odometer	38787 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	225/55R19	TOYO		6 mm
	L/H Front Tyre	225/55R19	TOYO		6 mm
	R/H Rear Tyre	225/55R19	TOYO		6 mm
	L/H Rear Tyre	225/55R19	TOYO		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	28/11/2024	Inspect Date /	Time	03/12/2024 (01:26 PM)
	Survey held at	N-51 AUTOMOTIVE PTE LTD			
		2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a.					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				
	l				