

ESTIMATE OF REPAIR

Veh# : SLN8322C

Accident Date : 1/12/2024

Location : PIE CHANGI BEFORE EUNOS EXIT

Model:

HONDA HRV

18/5/2017 - 17/5/2027

3P:

SCA338K (NTUC)

Hui Rong
2017
JHRU18106X202475

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bonnet <i>Dented</i>	892.30	✓	
2	1 pc	Front bonnet insulator <i>New</i>	122.30	+	
3	8 pcs	Front bonnet insulator clip <i>New</i>		40.00	+
4	2 pcs	Front bonnet rubber seal R/L <i>New</i>	75.00	+	
5	2 pcs	Front bonnet center rubber seal R/L <i>New</i>	47.60	+	
6	2 pcs	Front bonnet rubber protector R/L <i>New</i>	47.60	+	
7	1 pc	Front bonnet mechanism lock <i>New Best</i>	95.00	✓	
8	2 pcs	Front headlamp R/L <i>Cracked</i>	3,569.00	✓	
9	2 pcs	Front headlamp lower bracket R/L <i>Cracked</i>	76.00	✓	
10	2 pcs	Front headlamp side bracket R/L <i>Cracked</i>	70.00	✓	
11	1 pc	Front grille <i>Cracked</i>	351.80	✓	
12	1 pc	Front grille H Logo <i>New</i>	23.40	✓	
13	1 pc	Front grille center chrome moulding <i>Cracked</i>	98.00	✓	
14	1 pc	Front grille outer cover <i>Cracked</i>	421.00	✓	
15	1 pc	Front grille center bracket <i>New</i>	76.00	+	
16	1 pc	Front grille upper cover <i>Cracked</i>	85.00	✓	
17	1 set	Front grille upper cover clip <i>New</i>		40.00	20
18	1 pc	Front bumper <i>Cracked</i> (534.00)	801.70	✓	534.00
19	2 pcs	Front bumper side retainer R/L <i>New</i>	41.20	+	
20	1 set	Front bumper clip <i>New</i>		50.00	30
21	1 pc	Front bumper lower lid <i>Cracked</i>	381.00	✓	
22	1 pc	Front bumper lower grille <i>Cracked</i>	77.50	✓	
23	1 pc	Front bumper tow hook cover <i>Cracked</i>	17.10	✓	
24	1 pc	Front bumper reinforcement <i>Best</i>	321.00	✓	
25	2 pcs	Front bumper reinforcement moulding garnish R/L <i>New</i>	70.00	+	
26	1 pc	Front bumper foglamp RH <i>Cracked</i>	327.70	✓	
27	1 pc	Front bumper foglamp cover RH <i>New</i>	50.00	✓	
28	1 pc	Air-con condenser <i>Dented</i>	568.20	✓	
29	1 pc	Air-con condenser garnish RH <i>New</i> DE	31.60	✓	
30	1 pc	Front horn <i>Cracked</i>	110.50	✓	

31	1 pc	Rear tailgate <i>Distorted</i>	1,008.60	✓	
32	1 set	Rear tailgate spoiler clip <i>pc n</i>		50.00	+
33	1 pc	Rear tailgate windscreen glass sealant <i>nc</i>		80.00	60
34	2 pcs	Rear tailgate windscreen glass moulding R/L <i>nc</i>	120.00	✓	
35	2 pcs	Rear tailgate windscreen glass moulding top & lower <i>nc</i>	120.00	✓	
36	1 pc	Rear tailgate windscreen glass inner seal <i>nc</i>		80.00	60
37	1 pc	Rear tailgate inner trim garnish <i>Emb'd</i>	180.00	✓	
38	1 set	Rear tailgate inner trim garnish clip <i>nc</i>		80.00	30
39	2 pcs	Rear tailgate damper R/L <i>nc n</i>	360.00	+	
40	1 pc	Rear tailgate mechanism lock <i>Repl</i>	190.00	✓	
41	1 pc	Rear tailgate mechanism lock striker <i>nc n</i>	27.50	+	
42	1 pc	Rear tailgate weatherstrip <i>Repl</i>	106.45	✓	
43	1 pc	Rear tailgate inner pull garnish <i>Del'd</i>	53.00	✓	
44	1 pc	Rear tailgate emblem - IVTEC <i>nc</i>	42.20	✓	
45	1 pc	Front no. plate <i>Best</i>		35.00	-
46	1 pc	Front no. plate holder <i>Del'd</i>		50.00	-
47	1 pc	Front headlamp panel <i>Repl'd</i>	576.00	✓	
48	1 pc	Front radiator (Auto) <i>Repl'd</i>	1,376.00	✓	
49	1 pc	Front radiator coolant <i>nc</i>		50.00	✓
50	2 pcs	Front fender R/L (Repair) <i>Repis</i>			
51	1 pc	Front fender arch garnish RH <i>nc n</i>	220.00	+	
52	1 set	Front fender arch garnish clip RH <i>nc n</i>		30.00	+
53	1 pc	Rear exhaust silencer <i>nc n Repis</i>	517.70	+	
54	1 pc	Rear exhaust silencer gasket <i>nc</i>	48.30	+	
55	1 pc	Rear tailgate emblem - HRV <i>nc</i>	65.80	✓	
56	1 pc	Rear tailgate outer garnish <i>Emb'd</i>	220.00	✓	
57	1 pc	Rear tailgate outer garnish 'H' Logo <i>nc</i>	28.00	✓	
58	1 set	Rear tailgate outer garnish clip <i>nc</i>		50.00	20
59	2 pcs	Rear tailgate reflector R/L <i>RH ut</i>	826.40	413.20	
60	1 pc	Rear no. plate <i>Best</i>		30.00	✓
61	1 pc	Rear no. plate holder <i>Del'd</i>		50.00	30
62	2 pcs	Rear taillamp R/L <i>RH Cut</i>	949.20	474.60	
63	2 sets	Rear taillamp clip R/L <i>nc n</i>		60.00	+
64	1 pc	Rear bumper <i>Repl'd</i>	581.70	✓	
65	2 pcs	Rear bumper side R/L <i>RH & Del'd</i>	390.00	195	
66	2 pcs	Rear bumper side retainer R/L <i>nc n</i>	46.00	+	
67	1 set	Rear bumper clip <i>nc</i>		50.00	30
68	1 set	Rear bumper reverse sensor (4 eye) <i>Repl'd</i>		400.00	280
69	1 pc	Rear bumper reflector RH <i>Emb'd</i>	141.10	✓	
70	1 pc	Rear bumper lower cover <i>Repl'd</i>	250.00	✓	

71	2 pcs	Rear fender R/L (Repair) <i>R/L</i>				
72	1 pc	Rear fender arch garnish RH <i>Del'd</i>	195.00			
73	1 set	Rear fender arch garnish clip RH <i>in</i>		30.00		20
74	2 pcs	Rear fender inner trim garnish R/L <i>R/L Del'd</i>	590.00		295	
75	2 sets	Rear fender inner trim garnish clip R/L <i>in</i>		80.00		30
76	1 pc	Rear end panel <i>Del'd</i>	477.90			
77	1 pc	Rear end panel inner top garnish <i>Del'd</i>	98.00			
78	1 set	Rear end panel inner top garnish clip <i>in</i>		50.00		10
79	1 pc	Rear end panel sealant <i>in</i>		60.00		
80	1 pc	Rear end panel Antenna sensor <i>Del'd</i>	68.10			
81	1 pc	Rear end panel Buzzer sensor <i>Del'd</i>	85.20			
82	1 pc	Rear floor panel (Repair) <i>R/L</i>				
83	1 pc	Rear floor panel inner top cover <i>for</i>	430.30			310
84	1 pc	Rear floor panel compartment tray garnish <i>Del'd</i>	485.30			325
		<i>1609675 SN: 843</i>	Sub Total:	19,721.25	1,425.00	0.00
				20%	0%	0%
		<i>12877.4</i>	After Less %:	15,777.00	1,425.00	0.00
		Labour				
1		To remove & refix accident damaged parts & realign accident affected area.	2,000.00			1600
2		To spray paint on affected area.	2,200.00			1800
3		To remove & refix air-con condenser & refilling gas.	150.00			60
4		To remove & refix rear tailgate windscreen glass.	150.00			120
5		To remove & refix rear tailgate mechanism & check for function.	80.00			60
6		To remove & refix rear side covering, trim garnish & other attachment parts.	120.00			60
7		To remove & refix exhaust silencer. <i>3640</i>	80.00			x
8		To check wiring & rewire parking sensor.	80.00			✓
9		To rust proof affected area.	120.00			60
		Sub Total:		4,980.00		
		Total:		22,182.00		

Chan San Choon
Director

Pip Eng. AAE MIMI MSAE (Aust)

Link Auto Consultants hence notify

the Repairer of the following:

- To resurvey before and after spray painting.
- To display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

bizSAFE
S T R

AL 8778 1999
24 hr accident call

Mobil 1

SLN8322C ESTIMATEPg3

total 17362.40
L/S: 13.8K x/s 03/12/24
not dyn 12