

12 wDng



2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Xiao Chun.

Veh# : YN9657B

Model: HINO

Accident Date : 28/11/2024

(30/10/2015 - 29/10/2025)

Location : JOO KOON WAY

3P: XD3906L (NTUC)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear tailgate 60 KM/H sticker		25.00	X
2	1 pc	Rear tailgate 23 PAX sticker		25.00	X
3	1 pc	Rear tail gate sticker		150.00	X
4	1 pc	Rear mud flap torn		600.00	350
5	1 pc	Front Rh air duct Dehnd	710.20	✓	
6	1 pc	Front Rh B pillar Dehnd	910.00	✓	
7	1 pc	Front door RH Repair	1482.00	X	
8	1 pc	Front door mechanism lock RH	778.50	X	
9	1 pc	Front door inner plastic seal cover RH	33.90	X	
10	1 pc	Front door guide rubber stopped RH	8.40	X	
11	1 pc	Front door weatherstrip RH	363.10	X	
12	1 pc	Front door RH advertisement		300.00	180
13	1 pc	Front Rh mud flap rear Dehnd	210.40	✓	
14	1 pc	Rear carriage front wooden support Smashed		2000.00	1000.
15	1 pc	Rear tailgate		2000.00	X
16	1 pc	Rear tail lamp RH	280.00	X	
17	4 pcs	Rear tailgate hinges	720.00	X	
18	1 pc	Rear tailgate 60 KM/H sticker		25.00	X
19	1 pc	Rear tailgate 23 KM/H sticker		25.00	X
20	1 pc	Rear tailgate advertisement sticker		300.00	X
21	8pcs	Body vertical wooden planks R/L 5 pieces could		12000.00	4000.
22	9 pcs	Floor horizontal wooden member 6 pieces could		5400.00	2400.

23	2 pcs	Floor horizontal checker panel R/L		400.00	x	
24	2 pcs	Body vertical wooden member R/L	} <i>Sp m</i>	2600.00	+	
25	2 pcs	Body vertical wooden member checker panel R/L		400.00	+	
26	6 pcs	Body vertical wooden member U bracket R/L		900.00	+	
27	2 pcs	Body vertical wooden member U bracket (small) R/L		200.00	x	
28	1set	bolt and nut <i>new</i>		300.00	150.	
29	1 pc	Rear canopy assy <i>torn</i>		4500.00	2200	
		<i>183060 SN: 10280</i>	Sub-Total:	5,496.50	32,150.00	0.00
		<i>1647.54</i>		10%	0%	0%
			After Less %:	4,397.20	32,150.00	0.00
		<u>Labour</u>				
1		To repair cabin		1,200.00	<i>400.</i>	
2		To remove & refix door mechanism.		60.00	+	
3		To supply labor and equipment to repait rear deck		1,800.00	<i>1000</i>	
4		To spray paint on accident affected area.		1,400.00	<i>600</i>	
			Sub-Total:	4,460.00		
			Total:	41,007.20		
			After less 20%:	32,805.76		

Chan
Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)

Admin
1/2 03/2/24
11 Days: (11 days)



AL 8778 1999
24 hr accident call



total: 13827.54
1/2 11.1K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/a . . . spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: