AB ENGINEERING PTE LTD

Co. Reg No: 202117273R

10 KAKI BUKIT ROAD 2 #01-25, FIRST EAST CENTRE, SINGAPORE 417868 Tel: 8858 6282

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

GBC 3514 Vehick

有规则统

Report No

Chassis No:

Date

: 11/29/24

Engine MAKE: NISSAN

EURO

MODE ABS Al

TYPE

: COMMERCIAL

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Replacement of Da	amaged Parts
-------------------	--------------

	Trining Of Palling Stu 1 at 13		-
S/No.	<u>Description</u>	Qty.	Our Recommendation
1	Headlamp - RH / UK	1	394.30
2	Headlamp lowered garnish - RH	1	331.60
3	Front bumper / RK	1	541.50
4	Front bumper retainer - RH / K	1	60.40
5	Front bumper clips / h/k	4	40.00 31 -
6	Front bumper lowered garnish X N \(\chi\)	1	231.60
7	Front bumper lowered garnish clips X Mn	6	60.00
8	Front fender - RH	1	671.70
9	Front bumper reinforcement X 11	1	625.60
10	Door Signal Light (100 No. 5901 194 R4) / BR	1	92.70
11	Reinforcement lowered garnish - RH X MM	1	250.70 15.8/
12	Front Fander inner liner - RH / RK	1	962.30
13	Front Bonnet X K		\$4,316.60
		Less 10%	\$431.66
			\$3,884.94
	an.	Total (P)	33,004.54
	S/N		\$10.00
1	Position light bulb X	1	\$10.00 \$20.00
2	Panel Marking X	1	\$10.00
3	Signal light bulb X	1 T-4-1/(SAD)	\$40.00
		Total (S/N)	340.00
	T-	-1 (D4- 6 COD	\$3,924.94
	10	tal (Parts & S/N):	\$3,924.94
Labou	· Charges		
_	To the delication of the Late of Day		\$60.00 30
•	To checking wiring for head lamp RH		\$60.00
	To dismantle and replace of the accident damaged parts; to heat/weld,		
*	cut-off the reinforcement, panels, front fender, front bumpe etc		\$1,000.00 500
	including knocking, repair, reshape and adjust of same.		9
			C =
	To putty and spray painting on accident panels, lowered garnish RH,		\$1,200.00 600
	etc including knocking, repair, reshape and adjust of same.		
			_
•	To apply rustproofing on the repaired and replaced panels.		\$100.00 <i>30</i>
			_
		Total Labour:	\$2,360.00
	Final Repair Cost to Vehicle No: GBC351Y		
			\$6,284.94
	Amount Lump Sum Discount -20% Stew (LKK)		\$1,256.99
			\$5,027.95
	Add GST 9% 3 //2 /24 // 1/	101	\$452.52
	Grand Total		\$5,480.47
	Total Add GST 9% Grand Total 3//2/24, 1/. 1/.		
	V. C		
	41.5		
	10 11	,	
		11	
	J 1	J	
	LI da	15	
	1 1.0	7)	
		1	