AB ENGINEERING PTE LTD

Co. Reg No: 202117273R

10 KAKI BUKIT ROAD 2 #01-25, FIRST EAST CENTRE, SINGAPORE 417868 Tel: 8858 6282

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

GBC 3514 Vehick Chassis No:

有规则统

Report No

: 11/29/24

No illegal modification(s) is allowed

. Third party survey is on a "Without Prejudice" basis

LKK Auto Consultants hence notify the Repairer of the following:

To display damaged part(s) during resurvey

To resurvey before/after spray painting

Parts prices are subject to confirmation

· Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MAKE: NISSAN

MODE ABS Al **EURO**

Engine

TYPE

Date

: COMMERCIAL

Replacement of Damaged Parts

S/No.	Description	Qtx.	Our Recommendation	
1	Headlamp - RH	1 1	394.30	/
2	Headlamp lowered garnish - RH	i	331.60	/
3	Front bumper / RR	- 	541.50	1
4	Front bumper retainer - RH	i	60.40	/
5		4	40.00	31-
6		1 i II	231.60	3
7	Front bumper lowered garnish X	6	60.00	
8	Front bumper lowered garnish clips X MM		671.70	1
9	Front fender - RH / W		625.60	•
_	Front bumper reinforcement X	1	54.20	
10	Door Signal Light (100 No. 54nd 14M R4) / BK	1	92.70	
11	Reinforcement lowered garnish - RH	1 1		15.81
12	Front Fander inner liner - RH / RK	1	250.70	13.07
13	Front Bonnet X	1	962.30	
			\$4,316.60	2,241.7
		Less 10%	\$431.66	-10%
		Total (P)	\$3,884.94	2,017.53
	S/N			2,017.33
1	Position light bulb X nn	1	\$10.00	
2	Panel Marking X NN	1	\$20.00	
3	Signal light bulb X nn	1	\$10.00	
	Section 1911 Control 1911	Total (S/N)	\$40.00	
		roun (o/11)		•
		Tatal (Danta & COD).	\$3,924.94	•
		Total (Parts & S/N):	33,924.94	
. 10	12			
abou	r Charges			
				70
*	To checking wiring for head lamp RH		\$60.00	30
	To dismantle and replace of the accident damaged parts; to heat/we			
	cut-off the reinforcement, panels, front fender, front bumpe etc	eia,	\$1,000.00	500
	including knocking, repair, reshape and adjust of same.		\$1,000.00	500
	including knocking, repair, restape and adjust of same.			
	To putty and spray painting on accident panels, lowered garnish R	**		ſ.,
		н,	\$1,200.00	600
	etc including knocking, repair, reshape and adjust of same.			
	To apply rustproofing on the repaired and replaced panels.		\$100.00	30
				J
		Total Labour:	\$2,360.00	1160
		Iotal Labour.	02,000.00	1100
	T ID I C II VIII No CDC251V			
	Final Repair Cost to Vehicle No : GBC351Y			
	Amount (1 // // // // // // // // // // // // //		\$6,284.94	
	Amount Lump Sum Discount -20%		\$1,256.99	3177.53
	Total		\$5,027.95	0.77.00
	Add GST 9% 3 //2 /24 //	1101	\$452.52	1/0 0.540.00
	Grand Total	, ,,,,,,,	\$5,480.47	L/S - 2,542.02
	Grand Total	(00,10011	= 2550
	1.00	_		
	Total Add GST 9% Grand Total 3/12/24, //			
	m 1			
	M 1 Lls			
	L/s	ı		
	L/S L/S	((1)		
	L/S L/A	l m		
	L/S L/S	liy		
	L/S L) A)	l ry		
	L/S L/S L/A	l my		