



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 4602U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOT LID LOGO BADGE	NOT NECESSARY	51.00	-
1	BOOT LID EMBLEM "MAZDA 6"	NOT NECESSARY	46.00	-
1	BOOT LID EMBLEM "SKYACTIV TECHNOLOGY"	NOT NECESSARY	81.00	-
1	REAR BUMPER	DEFORMED	1,261.00	1,261.00
2	REAR BUMPER SIDE RETAINER RH/LH@2*\$42	NOT NECESSARY	84.00	-
1	REAR BUMPER TOWING COVER	NOT NECESSARY	30.00	-
2	REAR REFLECTOR RH/LH@2*\$53	NOT NECESSARY	106.00	-
1	END PANEL (NPA)	NOT NECESSARY	-	-
1	BOOT LID (NPA)	NOT NECESSARY	-	-
	LESS 20% DISCOUNT		-331.80	-252.20
			1,327.20	1,008.80
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER CLIP (SN)	NECESSARY	35.00	35.00
1	REAR BUMPER LOWER GARNISH CLIP (SN)	NOT NECESSARY	30.00	-
1	REAR CAR PLATE WITH HOLDER (SN)	NOT NECESSARY	35.00	-
1	REAR REVERSE SENSOR (SN)	CUT	200.00	200.00
			300.00	235.00
<u>LABOUR</u>				
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS.		800.00	200.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		800.00	200.00
	TO REMOVE AND REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL.	NOT NECESSARY	90.00	-
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	60.00	-
	TO REMOVE AND REPLACE REAR REVERSE SENSOR.		100.00	30.00
			1,850.00	430.00
GRAND TOTAL			3,477.20	1,673.80

Report Ref No. CS/SPF24120037/Tnh3m4(N)



RECOMMENDED COST OF REPAIRS			1,673.80
------------------------------------	--	--	-----------------

Report Ref No. CS/SPF24120037/Tnh3m4(N)

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,600-\$2,000

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.