



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF24120037/Tnh3m4(N)
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1 HEMMANT ROAD SINGAPORE 438675		Date:	16/01/2025
ATTN: LAI PENG CHONG		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 5204T	Veh. Inspected	SKZ 4602U
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2024/061(CF)	Excess (\$)	0.00
Assign From	LAI PENG CHONG	Assign Date	03/12/2024
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 6	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JM6GJ1072G0222917	Colour	RED
Odometer	94207 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/55R17	BRIDGESTONE	6 mm
L/H Front Tyre	225/55R17	BRIDGESTONE	6 mm
R/H Rear Tyre	225/55R17	BRIDGESTONE	6 mm
L/H Rear Tyre	225/55R17	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	29/08/2024	Inspection Date	20/12/2024
Survey held at	42 TOH GUAN ROAD EAST #01-79 ENT HUB S 608583		
Repairer	WAH HONG MOTORS & CREDIT PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	