



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref	: WH3549
Vehicle No.	: SKZ4602U
Make & Model	: MAZDA 6

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Boot lid logo badge		51.00 x	} nn x
1	Boot lid emblem "MAZDA 6"		46.00 x	
1	Boot lid emblem "SKYACTIV TECHNOLOGY"		81.00 x	
1	Rear bumper		1261.00	de ✓
1	Rear bumper side retainer RH/LH@2*\$42		84.00	LH x nn, RH - X nn
1	Rear bumper towing cover		30.00 x	↑ nn
1	Rear reflector RH/LH@2*\$53		106.00	LH x nn, RH - X nn
1	End panel (Repair refer to labour)		0.00	x nn
1	Boot lid (Repair refer to labour)		0.00	x nn
			1659.00	20% 1261 20% = 1008,80
Part Items Total:			-331.80	
			1327.20	
<u>SPECIAL NETT ITEMS</u>				
1	Rear bumper clip		35.00	rel ✓
1	Rear bumper lower garnish clip		30.00	x nn
1	Rear car plate with holder		35.00	x nn
1	Rear reverse sensor		200.00	cut ✓
SN Items Total:			300.00	235
Total Parts:			1627.20	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref	: WH3549
Vehicle No.	: SKZ4602U
Make & Model	: MAZDA 6

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
LABOUR			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00	200
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00	200
3	To remove and refix wiring system at accident damaged area and check for all electrical	90.00	x n
4	To perform anti-rust treatment on affected areas	60.00	x n
5	To remove and replace rear reverse sensor	100.00	30
Labour Total :		1850.00	430
TOTAL (PARTS & LABOUR):		3477.20	

Taujun 97495749
 wp 20/12/24 R 1045
 taujun e lkkanto.com
 2 days
 p/p using before paint.

1008.80
 235
 450
 \$1673.80
 - 2 days
 #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 te: