



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CS/LPC24120038/Uvh3e2
300 BEACH ROAD	Date:	31/12/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 5646M	Veh. Inspected	SLR 2060B
Policy No.	-	Coverage	0
Claim No.	24/24/24/VP05/030267	Excess	\$0.00
Assign From	GERALD POH	Assign Date	03/12/2024

### 2. Vehicle Details

Make & Model	HONDA HRV 1.5 DX (A)	C.C	1496
Engine No.	L15B4532362	Year of Reg.	03/08/2017
Chassis No.	JHMRU1810GX202363	Colour	BLUE
Odometer	147019 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/60R16	TOYO	6
L/H Front Tyre	215/60R16	TOYO	6
R/H Rear Tyre	215/60R16	MATRAX	6
L/H Rear Tyre	215/60R16	MATRAX	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	02/12/2024	Inspection Date	03/12/2024
Survey held at	AUTOBAY PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-11 SINGAPORE 417883		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days