

ASS. REC. BY:

REF:

0121 CS/CTI24120039/Kvh3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

Global

of

Insured: SMR 5977A

Policy No.

Claims No. SNM24D206764

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$43k 17/1/25 (Kenneth)

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

023

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SR 24180

Yr Regn:

17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1797

Colour

m.b. Beige

A/C:

Insured / Std / NI / NA

Sp. Reading

417070

T/Radio:

Insured / Std / NI / NA

Eng/No:

V E W 50

8031367

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Crown lande

Front

R/Bal.

d

mm

Rear

R/Bal.

d

mm

L/Bal.

p

mm

L/Bal.

p

mm

D.O.A.

1/124

D.O.I.

3/12/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/1/25 GIA & EM not ready

17/1/25

LS \$1750 confirmed with Jenny (red 3220.99, 64%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) TOTAL

Not Withheld
L/Sep 8 1750h
Picking After Rain

GLOBAL AUTO SPECIALIST PTE LTD

48 TOH GUAN ROAD EAST #06-99 ENTERPRISE HUB SINGAPORE 608586 TEL/FAX: 6464 9291 H/P: 9147 7675
BRANCH: 176 SIN MING DRIVE #05-14 SIN MING AUTOCARE SINGAPORE 575721 TEL/FAX: 6481 7675 H/P: 9639 1626
MAILING ADDRESS: 177 ANG MO KIO AVE 4 #04-911 SINGAPORE 560177
CO / GST REG NO.: 201018026D

3 days

ESTIMATE

Joyride.sg

BLK 177 Ang Mo Kio Ave 4
#04-911
Singapore 560177

TEL : 96391626

FAX :

c/o 176 Sin Ming Dr #05-14 Sin Ming Autocare Singapore 575721

No. : GSQ-SM-2412001

Date : 23-12-2024

Vehicle No. : SLR2418D

Make : TOYOTA

Model : PRIUS HYBRID

Accident Date : 29/11/2024

Page : 1 of 2

Item	Description	Qty	U/ Price S\$	Total S\$
1.	Rear bumper 765.10	1.0	Bu 1,015.00 ✓	1,015.00
2.	Rear bumper lower 552.30	1.0	Nd/Lu 654.96 ✓	654.96
3.	Rear bumper reinforcement 398.20	1.0	Py 521.00 ✓	521.00
4.	Rear bumper tow hook cover 45.10	1.0	Nd/Lu 82.70 ✓	82.70
5.	Rear bumper retainer	2.0	Lu 88.00 X	176.00
6.	Rear bumper bracket	2.0	Lu 54.00 X	108.00
7.	Rear bumper lower side cover	2.0	Lu 232.00 X	464.00
8.	Rear bumper upper side cover	2.0	Lu 395.00 X	790.00
9.	Tailgate "TOYOTA" logo	1.0	Lu 76.00 X	76.00
10.	Tailgate emblem "PRIUS"	1.0	Lu 59.00 X	59.00
11.	Tailgate emblem "HYBRID"	1.0	Lu 92.00 X	92.00
	Discount 25 %			-1,009.67
12.	Rear bumper clips	10.0	Lu 5.50 ✓	55.00
13.	Tailgate outer garnish clips	8.0	Lu 5.50 X	44.00
14.	Rear end panel top garnish clips	6.0	Lu 5.50 X	33.00
15.	Reverse sensor	1.0	Shore 280.00 200.00	280.00
16.	Labour to remove & replace affected parts for accident areas	1.0	800.00 300.00	800.00
17.	Spray paint on affected areas	1.0	600.00 350.00	600.00
18.	To apply anti rust coating on affected areas	1.0	Lu 80.00 X	80.00
19.	To check wiring functions	1.0	50.00 10.00	50.00

258

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

GLOBAL AUTO SPECIALIST PTE LTD

48 TOH GUAN ROAD EAST #06-99 ENTERPRISE HUB SINGAPORE 608586 TEL/FAX: 6464 9291 H/P: 9147 7675
BRANCH: 176 SIN MING DRIVE #05-14 SIN MING AUTOCARE SINGAPORE 575721 TEL/FAX: 6481 7675 H/P: 9639 1626
MAILING ADDRESS: 177 ANG MO KIO AVE 4 #04-911 SINGAPORE 560177
CO / GST REG NO.: 201018026D

ESTIMATE

Joyride.sg

BLK 177 Ang Mo Kio Ave 4
#04-911
Singapore 560177

TEL : 96391626

FAX :

c/o 176 Sin Ming Dr #05-14 Sin Ming Autocare Singapore 575721

No. : GSQ-SM-2412001

Date : 23-12-2024

Vehicle No. : SLR2418D

Make : TOYOTA

Model : PRIUS HYBRID

Accident Date : 29/11/2024

Page : 2 of 2

Item	Description	Qty	U/ Price S\$	Total S\$
------	-------------	-----	-----------------	--------------

SINGAPORE DOLLAR FIVE THOUSAND FOUR HUNDRED EIGHTEEN AND CENTS
THIRTY EIGHT ONLY

Sub Total 4,970.99

Add GST 9% 447.39

Net Total 5,418.38

Validity :

Delivery Term :

For and on behalf of
GLOBAL AUTO SPECIALIST PTE LTD



Authorised Signature & Company Stamp