

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 03.12.20204

Xiao Chan

TO : MS FIRST CAP MOTOR CLAIMS DEPTS
VEHICLE NO : SKL9677U
MODEL : BMW 316I
DATE OF ACCIDENT : 25.11.2024
TIME OF ACCIDENT : 18:50 HOURS

WBA3A16000NS36171
2014

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Delud</i>	1	\$ 1,674.60	\$ 1,674.60
2	FRONT BUMPER LOWER GRILLE <i>he m</i>	1	\$ 143.90	\$ 143.90
3	FRONT BUMPER LOGO <i>New</i>	1	\$ 160.00	\$ 160.00
5	FRONT BUMPER NOZZLE COVER RH <i>Cracked</i>	1	\$ 61.95	\$ 61.95
6	FRONT BUMPER NOZZLE WITH MOTOR RH <i>Cracked</i>	1	\$ 174.40	\$ 174.40
11	FRONT BUMPER TOWING COVER <i>he m</i>	1	\$ 35.00	\$ 35.00
12	FRONT BUMPER TOP RUBBER <i>he m</i>	1	\$ 35.45	\$ 35.45
13	FRONT BUMPER BOTTOM SIDE GARNISH <i>all</i>	2	\$ 19.85	\$ 39.70
14	FRONT BUMPER FOG LAMP RH <i>Cracked</i>	1	\$ 275.10	\$ 275.10
15	FRONT BUMPER FOG LAMP COVER RH <i>Cracked</i>	1	\$ 183.10	\$ 183.10
16	FRONT BUMPER SIDE INNER AIR DUCT <i>he m</i>	2	\$ 187.00	\$ 374.00
17	FRONT BUMPER SIDE AIR DUCT <i>he m</i>	2	\$ 135.00	\$ 270.00
18	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$ 894.35	\$ 894.35
19	FRONT BUMPER SPONGE <i>Cracked</i>	1	\$ 356.00	\$ 356.00
20	FRONT BUMPER LOWER BEAM <i>Best</i>	1	\$ 431.00	\$ 431.00
22	FRONT GRILLE C/W CHROME <i>Best</i>	2	\$ 285.00	\$ 570.00
49	FRONT AIR GUARD UPPER <i>Cracked</i>	1	\$ 350.00	\$ 350.00
50	FRONT AIR GUARD LOWER <i>he m</i>	1	\$ 275.00	\$ 275.00
21	ENGINE UNDERCOVER <i>he m</i>	1	\$ 190.80	\$ 190.80
55	FRONT FENDER RH <i>he m</i>	1	\$ 1,355.00	\$ 1,355.00
24	FRONT FENDER COWLING <i>to m</i>	2	\$ 169.95	\$ 339.90

TO : MS FIRST CAP MOTOR CLAIMS DEPTS
 VEHICLE NO : SKL9677U
 MODEL : BMW 316I
 DATE OF ACCIDENT : 25.11.2024
 TIME OF ACCIDENT : 18:50 HOURS

25	HEADLAMP (HID) <i>Cancel RH</i>	2	\$ 3,865.20	\$ 7,730.40	<i>3865.20</i>
26	HEADLAMP LOWER BRACKET <i>Cancel Bent RH</i>	2	\$ 78.60	\$ 157.20	<i>78.60</i>
27	HEADLAMP TOP BRACKET <i>to m</i>	2	\$ 53.20	\$ 106.40	<i>+</i>
28	FRONT FENDER RH <i>Remove Repair</i>	1	\$ 889.00	\$ 889.00	<i>+</i>
29	FRONT FENDER COWLING RH <i>to m</i>	1	\$ 161.20	\$ 161.20	<i>+</i>
30	FRONT FENDER SUPPORT BRACKET RH <i>to m</i>	1	\$ 185.60	\$ 185.60	<i>+</i>
31	FRONT FENDER EXTEND GARNISH RH <i>to m</i>	1	\$ 138.00	\$ 138.00	<i>+</i>
32	FRONT ABS SENSOR RH	1	\$ 383.50	\$ 383.50	<i>+</i>
33	FRONT LOWER ARM RH (FRONT)	1	\$ 432.10	\$ 432.10	<i>+</i>
34	FRONT LOWER ARM RH (REAR)	1	\$ 493.20	\$ 493.20	<i>+</i>
35	FRONT LOWER ARM LINK ROD RH	1	\$ 234.60	\$ 234.60	<i>+</i>
36	FRONT SHOCK ABSORBER RH	1	\$ 541.80	\$ 541.80	<i>+</i>
37	FRONT KNUCKLE ARM RH	1	\$ 667.30	\$ 667.30	<i>+</i>
38	FRONT KNUCKLE BEARING WITH HUB RH	1	\$ 523.10	\$ 523.10	<i>+</i>
39	FRONT SIDE MIRROR RH <i>to m</i>	1	\$ 1,780.50	\$ 1,780.50	<i>+</i>
40	SIDE SKIRT RH <i>to m</i>	1	\$ 388.90	\$ 388.90	<i>+</i>

9058.25
8605.33

TOTAL PRICE \$ 23,002.05
 LESS 5% \$ 1,150.10
 SUB TOTAL PRICE \$ 21,851.95

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 120.00	\$ 120.00
2	FRONT FENDER COWLING CLIP RH (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
3	FRONT FENDER EXTEND GARNISH CLIP RH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
4	FRONT WHEEL TYRE RH <i>new</i>	1	\$ 850.00	\$ 850.00
5	FRONT WHEEL RIM RH <i>new</i>	1	\$ 1,600.00	\$ 1,600.00
6	BRAKE OIL <i>new</i>	1	\$ 60.00	\$ 60.00

60

TOTAL \$ 2,770.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	<i>400</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	<i>400</i>

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
VEHICLE NO : **SKL9677U**
MODEL : **BMW 316I**
DATE OF ACCIDENT : 25.11.2024
TIME OF ACCIDENT : 18:50 HOURS

3	TUFF COAT	\$	350.00	30
4	WIRING CHECK	\$	250.00	30
5	REFOCUS HEADLAMP BEAM	\$	80.00	X
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$	1,200.00	X
7	TO PRESS FRONT WHEEL BEARING	\$	80.00	X
8	FOUR WHEEL ALIGNMNET	\$	150.00	X
9	RESET ABS LIGHT	\$	650.00	X
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$	1,200.00	150

1010

TOTAL \$ **6,560.00**
TOTAL PARTS COST : \$ 24,621.95
TOTAL LABOUR COST : \$ 6,560.00
TOTAL REPAIR COST : \$ 31,181.95

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER,YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP:8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin C
2/s 02/12/24

03 days

blat: 9675.33

c/s: 7750

7750