

ESTIMATE

3/12/2024

China Taiping Insurance (Singapore) Pte. Ltd
 83 Anson Road #15-00
 Springleaf Tower
 Singapore 079909

Page: 1
 Vehicle No: SMF5622L
 Vehicle Model: MIT ECLIPSE CROSS
 Est No: CBMQ24120025
 Claims ref:
 Accident Date: 28/11/24
 In Charge: BRIAN
 Remarks:

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel : (65) 6476 3333
 Fax : (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722
 Tel : (65) 6272 3892
 Fax : (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

No	Description	Qty	U. Price	Amounts S\$
LIST ITEMS:				
1	F/ BONNET	1 PC	\$ 1,215.60	\$ 1,215.60 <i>bt</i>
2	F/ BONNET HINGE LH	1 PC	\$ 128.00	\$ 128.00 <i>bt</i>
3	F/ BONNET HINGE RH	1 PC	\$ 128.00	\$ 128.00 <i>bt</i>
4	F/ BONNET INSULATOR	1 PC	\$ 272.40	\$ 272.40 <i>de</i>
5	F/ BONNET LOCK	1 PC	\$ 262.40	\$ 262.40 <i>bt</i>
6	F/ GRILLE ASSY	1 PC	\$ 696.30	\$ 696.30 <i>cur</i>
7	F/ GRILLE BASE	1 PC	\$ 226.40	\$ 226.40 <i>cur</i>
8	F/ BUMPER	1 PC	\$ 1,210.00	\$ 1,210.00 <i>de</i>
9	F/ BUMPER LOWER LIP	1 PC	\$ 479.00	\$ 479.00 <i>cut</i>
10	F/ BUMPER GARNISH COVER	1 PC	\$ 546.30	\$ 546.30 <i>de</i>
11	F/ BUMPER CHROME MLDG TOP RH	1 PC	\$ 374.40	\$ 374.40 <i>cur</i>
12	F/ BUMPER CHROME MLDG LOWER RH	1 PC	\$ 226.80	\$ 226.80 <i>cur</i>
13	F/ BUMPER CENTER GRILLE	1 PC	\$ 215.00	\$ 215.00 <i>de</i>
14	F/ BUMPER DISTANCE SENSOR RH	1 PC	\$ 340.00	\$ 340.00 <i>dis</i>
15	F/ BUMPER DISTANCE SENSOR HOLDER RH	1 PC	\$ 33.60	\$ 33.60 <i>dis</i>
16	F/ BUMPER REINFORCEMENT <i>- photo</i>	1 PC	\$ 772.00	\$ 772.00 <i>bt</i>
17	F/ BUMPER UPPER SUPPORT PANEL	1 PC	\$ 543.00	\$ 543.00 <i>bt</i>
18	F/ BUMPER UPPER SUPPORT PANEL TOP COVERING	1 PC	\$ 446.00	\$ 446.00 <i>cut</i>
19	F/ BUMPER SIDE RETAINER RH	1 PC	\$ 89.40	\$ 89.40 <i>de</i>
20	F/ BUMPER LAMP RH	1 PC	\$ 646.00	\$ 646.00 <i>cur</i>
21	F/ BUMPER LAMP CHROME RING RH	1 PC	\$ 166.00	\$ 166.00 <i>cut</i>
22	F/ BUMPER LAMP BRACKET RH	1 PC	\$ 115.00	\$ 115.00 <i>de</i>
23	F/ HEAD LAMP LH	1 PC	\$ 2,240.00	\$ 2,240.00 <i>cur</i>
24	F/ HEAD LAMP RH	1 PC	\$ 2,240.00	\$ 2,240.00 <i>cur</i>
25	F/ HEAD LAMP INJECTOR NOZZLE ASSY RH	1 PC	\$ 293.00	\$ 293.00 <i>dis</i>
26	F/ HEAD LAMP INJECTOR NOZZLE COVER RH	1 PC	\$ 88.60	\$ 88.60 <i>mis</i>
27	F/ SUPPORT PANEL <i>- photo</i>	1 PC	\$ 1,210.00	\$ 1,210.00 <i>bt</i>
28	F/ AIR COND CONDENSOR	1 PC	\$ 940.00	\$ 940.00 <i>bt</i>
29	F/ AIR COND LIQUID TUBE	1 PC	\$ 424.00	\$ 424.00 <i>Xun</i>
30	F/ AIR COND COOLING PIPE	1 PC	\$ 533.00	\$ 533.00 <i>Xun</i>
31	F/ RADIATOR	1 PC	\$ 1,460.00	\$ 1,460.00 <i>bt</i>
32	F/ HORN	1 PC	\$ 166.00	\$ 166.00 <i>bt</i>
33	F/ WIPER TANK ASSY	1 PC	\$ 248.40	\$ 248.40 <i>de</i>
34	F/ FENDER LH	1 PC	\$ 787.00	\$ 787.00 <i>bt</i>
35	F/ FENDER RH	1 PC	\$ 787.00	\$ 787.00 <i>bt</i>
36	F/ FENDER ARCH EXTENTION COVER RH	1 PC	\$ 277.60	\$ 277.60 <i>Xun</i>

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

3/12/2024

China Taiping Insurance (Singapore) Pte. Ltd
83 Anson Road #15-00
Springleaf Tower
Singapore 079909

Page: 1
Vehicle No: SMF5622L
Vehicle Model: MIT ECLIPSE CROSS
Est No: CBMQ24120025
Claims ref:
Accident Date: 28/11/24
In Charge: BRIAN
Remarks:

No	Description	Qty	U. Price	Amounts S\$
	LIST TOTAL S\$		19591.60	\$ 20,826.20
	10% DISCOUNT S\$		17632.74	\$ (2,082.62)
				<u>\$ 18,743.58</u>

SPECIAL NET ITEMS:

1	F/ BONNET INSULATOR CLIPS	1	PC \$ 40.00	\$ 40.00 <i>2000 ✓</i>
2	F/ GRILLE CLIPS	1	PC \$ 40.00	\$ 40.00 <i>2000 ✓</i>
3	F/ BUMPER CLIPS	1	PC \$ 50.00	\$ 50.00 <i>3000 ✓</i>
4	F/ NUMBER PLATE + FRAME	1	PC \$ 40.00	\$ 40.00 <i>60 ✓</i>
5	F/ RADIATOR COOLANT	1	PC \$ 60.00	\$ 60.00 <i>na ✓</i>
6	F/ FENDER LINER CLIPS	1	PC \$ 40.00	\$ 40.00 <i>X 20 ✓</i>

SPECIAL NET TOTAL S\$

\$ 270.00 *170*

LABOUR CHARGE:

1	TO REMOVE, REPLACE & REFIT AIR COND CONDENSOR, AIR COND LIQUID TUBE, AIR COND COOLING PIPE, RADIATOR, RADIATOR FAN ASSY & ETC.			<i>photo 100 ✓</i> \$ 120.00
2	TO REMOVE, REPLACE & REFIT FRONT BUMPER DISTANCE SENSOR, DISTANCE SENSOR WIRING HARDNESS & ETC. TO EFFECT REPLACE OF FRONT BUMPER			<i>50</i> \$ 100.00
3	TO REMOVE, REPLACE, REPAIR, READJUST & CHISEL FRONT ACCIDENT AREAS SUCH AS FRONT BONNET, FRONT BUMPER, FRONT H/LAMP L/R, FRONT SUPPORT PANEL, FRONT FENDER L/R, FRONT GRILLE, FRONT WHEEL HOUSE & ETC. BACK TO ORIGINAL CONDITONS			<i>700</i> \$ 850.00
4	TO HYDRAULICALLY JACK & REALIGN FRONT BOTH CHASSIS FRAME & ETC. BACK TO ORIGINAL CONDITIONS			<i>200 ✓ photo.</i> \$ 350.00
5	TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT SUPPORT PANEL, FRONT FENDER LH/RH, FRONT WHEEL HOUSE CHASSIS LH/RH			<i>1000</i> \$ 1,300.00
6	TO CHECK WIRING & ELECTRICAL SYSTEM			<i>40</i> \$ 80.00
7	TO REFILL AIR COND GAS & VACUUM			<i>X ✓</i> \$ 100.00

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

3/12/2024

China Taiping Insurance (Singapore) Pte. Ltd
83 Anson Road #15-00
Springleaf Tower
Singapore 079909

Page: 1
Vehicle No: SMF5622L
Vehicle Model: MIT ECLIPSE CROSS
Est No: CBMQ24120025
Claims ref:
Accident Date: 28/11/24
In Charge: BRIAN
Remarks:

No	Description	Qty	U. Price	Amounts S\$
8	TO DIAGNOSIS FAULTY CODE & RESET MEMORY			\$ 150.00

TOTAL LABOUR COST S\$

a) To Remove / Refit Engine Assy ~~4380~~ 200 2540

\$ 3,050.00

AMOUNT S\$ \$ 22,063.58
GST @ 9% \$ 1,985.72
AMOUNT DUE S\$ \$ 24,049.30

Customer's Signature

MOVA AUTOMOTIVE PTE LTD

17632.44

170
2540

20342.44

L/S \$16,250

7 days #

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjun 97495749 / 62563561

wp' 4/12/24 @ 230pm

L/S Resurvey after repair

tanjun @ lkhauto.com.

6 Days.