



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMC 6388Y

Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER (N)	DENTED	\$966.10	\$945.20
1	FRONT BUMPER FOG LAMP -LH (N)	CRACKED	\$286.90	\$286.90
1	FRONT BUMPER FOG LAMP COVER (N)	TWISTED	\$131.20	\$131.20
1	FRONT BUMPER BRACKET (N)	CRACKED	\$110.50	\$110.50
1	FRONT BUMPER REINFORCEMENT (N)	NOT NECESSARY	\$571.60	\$0.00
1	FRONT BUMPER SPONGE (N)	TORN	\$140.60	\$140.60
2	FRONT BUMPER SIDE RETAINERS -R/L @\$55.00 (N)	SERVICEABLE	\$110.00	\$0.00
1	FRONT FENDER -LH (N)	TO REPAIR SEE LABOUR	\$815.60	\$0.00
1	FRONT FENDER PROTECTOR (N)	GRAZED	\$535.20	\$535.20
1	FRONT FENDER INNER SHIELD (N)	SERVICEABLE	\$181.60	\$0.00
	<b>LESS 10.00%</b>		(\$384.93)	(\$214.96)
			<b>\$3,464.37</b>	<b>\$1,934.64</b>
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	\$60.00	\$30.00
			\$60.00	\$30.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK FRONT ELECTRICAL WIRING		\$50.00	\$20.00
	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS		\$600.00	\$400.00
	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER -LH		\$600.00	\$380.00
			\$1,250.00	\$800.00
<b>GRAND TOTAL</b>			<b>\$4,774.37</b>	<b>\$2,764.64</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>\$2,200.00</b>
Report Ref No: CS/AGI24120045/Uvh3m4				



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## **CKS**

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.