



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 ATTN: MONICA CHUNG			Ref: CS/AGI24120047/Avh3m4(N) Date: 04/04/2025 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBN 1773Z	Veh. Inspected	SMK 3130B
	Policy No.	P21031719R00	Coverage (\$)	0.00
	Claim No.	C20033207/MC	Excess (\$)	0.00
	Assign From	LAN BOON CHIN	Assign Date	03/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	HONDA HRV	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	JHMRU1810JX201479	Colour	BROWN
	Odometer	53562 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60R16	DUNLOP	6 mm
	L/H Front Tyre	215/60R16	DUNLOP	6 mm
	R/H Rear Tyre	215/60R16	DUNLOP	6 mm
	L/H Rear Tyre	215/60R16	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/11/2024	Inspection Date	03/12/2024
	Survey held at	BEST SOLUTION AUTOCARE PTE LTD 53 UBI AVE 1 #03-01 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	