

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0507/2024/KS
DATE : 29-Jun-24
WIP : 21086

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/7/2024

YOUR INSURED VEH NO : SKW 3157 K

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MS TAN SOCK HUA ANGELINE
ADDRESS : 78 HOUGANG AVENUE 7
#16-28
SINGAPORE 534260
TELEPHONE : HP +65 97332939
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : V5018532
VEHICLE NO : **SKV 6006 Z**
MODEL CODE : A3 CABRIOLET 1.4 TFSI
MODEL YEAR : 29/5/2015
ENGINE NO : CZC 261319
CHASSIS NO : WAUZZZ8V5F1140370
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Jun-24
PLACE OF ACCIDENT : PIE TOWARDS TUAS EXIT 27

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKV 6006 Z.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER PARKING AID.	S/N \$	280.00	✓
2	TO DISMANTLE AND RENEW BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS	\$	1,000.00	500
3	TO RESPRAY REAR BUMPER	\$	1,000.00	550
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	480.00	✓ 292
TOTAL LABOUR CHARGES		:	\$ 2,760.00	1622

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKV 6006 Z.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,483.00	Rx
2	REAR BUMPER FIXING PARTS	1	\$ 216.00	X NN
3	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 42.00	X NN
4	REAR BUMPER GUIDE SECTION PIN - LH / RH	2	\$ 75.00	X NN
5	REAR BUMPER SPOILER	1	\$ 297.00	X NN
6	REAR BUMPER REINFORCEMENT BEAM	1	\$ 736.00	X NN
7	REAR BUMPER LOWER BRACKET - LH / RH	2	\$ 34.00	X NN
8	REAR PARKING AID SENSOR	2	\$ 572.00	X NN
9	REAR PARKING AID SENSOR SEAL RING	4	\$ 11.00	XXXX NN
10	SUNDRIES		\$ 300.00	Xnn
TOTAL SPARE PARTS		:	\$ 4,766.00	
TOTAL LABOUR CHARGES		:	\$ 2,760.00	
GRAND TOTAL		:	\$ 7,526.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Tanfer 97495749* \$1622
SURVEYED DATE : *wp, 7/2/24 @ 11am* 3 DAYS #
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *3 days
Resurvey before paint / after paint
Tangfer e (handwritten)*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT