

T K LEE AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

MSIG INSURANCE (SINGAPORE) PTE.LTD.

4 SHENTON WAY

#21-01 SGX CENTRE 2

SINGAPORE 068807

F131Z

ESTIMATE

VEHICLE NO : SMP6594A
MAKE/MODEL : TOYOTA NOAH
ACC DATE : 03/12/2024

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
LIST PRICE			
1	1 FRONT BUMPER	1,210.66	1,210.66 ✓
2	1 FRONT BUMPER LOWER GRILLE -CTR	181.93	181.93 X
3	1 FRONT BUMPER FOG LAMP -LH	341.65	341.65 X
4	1 FRONT BUMPER FOG LAMP COVER -LH	110.25	110.25 ✓
5	1 FRONT BUMPER SPONGE	180.93	180.93 ✓
6	1 FRONT BUMPER REINFORCEMENT	599.62	599.62 ✓
7	2 FRONT BUMPER SIDE RETAINERS -R/L	110.25	220.50 X
8	1 FRONT BUMPER UNDERCOVER	180.93	180.93 X
9	1 FRONT FENDER -LH	861.13	861.13 X
10	1 FRONT FENDER INNER SHIELD -LH	154.43	154.43 X
11	1 FRONT HEADLAMP ASSY -LH	2,889.65	2,889.65 ✓
12	1 FRONT SUPPORT PANEL	1,160.50	1,160.50 X
13	1 RAD GRILLE -TOP	1,101.63	1,101.63 ✓
14	1 RAD GRILLE -BOTTOM	991.62	991.62 ✓
		800.20	10,185.43
		LESS 25%	2,546.36
			7,639.07

SPECIAL NETT ITEMS

1	1 (SET) FRONT BUMPER CLIP	50.00	50.00 30
2	1 FRONT BUMPER LOWER SPOILER	850.00	850.00 800
3	1 (SET) FRONT NUMBER PLATE	60.00	60.00 40
			960.00

LABOUR CHARGES :

1	TO CHECK FRONT ELECTRICAL WIRING	50.00 20
2	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	1,080.00 600
3	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	800.00 400
		1,930.00

Total :

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged parts for inspection
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 10,529.07

26892.94
252
5169.71
870
1020

Not Authorized
meray
Himzy
1/5 & 5600
Hays
wh... ..