



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE GST Registration No. 201118055N Company Registration No: 201118055N

not allowed
5/12/24
2/s \$1300/
2 days.
Tel: 96481018

Shen JinQuan
29 Compassvale Bow #12-38 Singapore 544758
Contact : 96481018

LKK Auto Consultants hence notify
the Repairer of the following:

- To display damaged parts, for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ESTIMATE

Code : C102127

Date in : 05/12/2024

Vehicle Num. : SLK3458T

Model : Nissan X-Trail 2.0 CVT ABS 4WD S/
R 7-STR

Chassis/Eng# : JN1JANT32Z0002981/MR20963235B

Acknowledged by Repairer

Signature:

Parts and Labour Assessment

Date:

Notified

Description of part	Qty	Unit Price	Amount
Rear bumper	1	771.80	771.80
Rear bumper reflector RH	1	68.90	68.90
Rear bumper reinforcement	1	663.20	663.20
Rear bumper side bracket RH	1	43.30	43.30
Rear bumper stay RH	1	217.90	217.90
Rear innershield RH	1	98.50	98.50
Rear wheel protector RH	1	180.90	180.90
Subtotal before discount			2,044.50
Percentage discount 10%			204.45
Sub-total 1			1,840.05
Rear bumper clips (set) (sn)	1 set	30.00	30.00
Reverse sensor (set) (sn)	1 set	280.00	280.00
Subtotal before discount			310.00
Percentage discount 0%			0.00
Sub-total 2			310.00
Parts-total			2,150.05

LABOUR

Description	Price
To remove, refix / renew reverse sensor assy and rectify for proper functioning.	120.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	800.00



Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE o PERFORMANCE GST Registration No. 201118055N Company Registration No: 201118055N

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical (Tuff-Kote) on repaired and replaced panel.

800.00 300

11 120.00 X

Labour Total

1,840.00

Parts & Labour Total

3,990.05

page 2

29527
102
847.43
30
740
1627.43
102
17301